

CAUTION

OSHA§1910.145(c)(2)(i) states "Caution signs shall be used only to warn against potential hazards or to Caution against unsafe practices." (ii) states "All employees shall be instructed that Caution signs indicate a possible hazard against which proper precaution should be taken."
This heading should not be used when there is a possibility of death or serious injury.

THE SIGNS OF A SAFE INDUSTRY

MATERIALS



CAUTION ACID

3x5 VPO C-000114
7x10 AL C-000121
FG C-000122
PL C-000123
VPO C-000124
10x14 AL C-000131
FG C-000132
PL C-000133
VPO C-000134
14x20 AL C-000141
PL C-000143
VPO C-000144

CAUTION ACID BE CAREFUL

3x5 VPO C-000214
7x10 AL C-000221
FG C-000222
PL C-000223
VPO C-000224
10x14 AL C-000231
FG C-000232
PL C-000233
VPO C-000234
14x20 AL C-000241
PL C-000243
VPO C-000244

CAUTION AREA IN FRONT OF ELECTRICAL PANEL MUST BE KEPT CLEAR FOR 36 INCHES OSHA REGULATIONS

3x5 VPO C-000614
7x10 AL C-000621
FG C-000622
PL C-000623
VPO C-000624
10x14 AL C-000631
FG C-000632
PL C-000633
VPO C-000634
14x20 AL C-000641
PL C-000643
VPO C-000644

CAUTION ASBESTOS HAZARD DO NOT DISTURB WITHOUT PROPER TRAINING AND EQUIPMENT

3x5 VPO C-000914
7x10 AL C-000921
FG C-000922
PL C-000923
VPO C-000924
10x14 AL C-000931
FG C-000932
PL C-000933
VPO C-000934
14x20 AL C-000941
PL C-000943
VPO C-000944

CAUTION ATTACH GROUNDING WIRE CLIPS

3x5 VPO C-001114
7x10 AL C-001121
FG C-001122
PL C-001123
VPO C-001124
10x14 AL C-001131
FG C-001132
PL C-001133
VPO C-001134
14x20 AL C-001141
PL C-001143
VPO C-001144

CAUTION AUTOMATIC EQUIPMENT WILL START AT ANY TIME

3x5 VPO C-001214
7x10 AL C-001221
FG C-001222
PL C-001223
VPO C-001224
10x14 AL C-001231
FG C-001232
PL C-001233
VPO C-001234
14x20 AL C-001241
PL C-001243
VPO C-001244

CAUTION BATTERY CHARGING STATION NO SMOKING OR OPEN FLAMES

3x5 VPO C-050114
7x10 AL C-050121
FG C-050122
PL C-050123
VPO C-050124
10x14 AL C-050131
FG C-050132
PL C-050133
VPO C-050134
14x20 AL C-050141
PL C-050143
VPO C-050144

CAUTION BEFORE ENTERING TEST FOR EXPLOSIVE ATMOSPHERE TEST FOR OXYGEN DEFICIENCY SUPPLY FRESH AIR TO WORK AREA

3x5 VPO C-050314
7x10 AL C-050321
FG C-050322
PL C-050323
VPO C-050324
10x14 AL C-050331
FG C-050332
PL C-050333
VPO C-050334
14x20 AL C-050341
PL C-050343
VPO C-050344

CAUTION BEFORE PROCEEDING WITH REPAIR WORK ALL SOURCES OF POWER TO THE MACHINE MUST BE TAGGED OUT AND/OR SECURED WITH A LOCKING DEVICE

3x5 VPO C-050414
7x10 AL C-050421
FG C-050422
PL C-050423
VPO C-050424
10x14 AL C-050431
FG C-050432
PL C-050433
VPO C-050434
14x20 AL C-050441
PL C-050443
VPO C-050444

CAUTION BEFORE YOU START LOCKOUT FOR SAFETY

3x5 VPO C-050514
7x10 AL C-050521
FG C-050522
PL C-050523
VPO C-050524
10x14 AL C-050531
FG C-050532
PL C-050533
VPO C-050534
14x20 AL C-050541
PL C-050543
VPO C-050544

CAUTION BEND KNEES WHEN LIFTING

3x5 VPO C-050614
7x10 AL C-050621
FG C-050622
PL C-050623
VPO C-050624
10x14 AL C-050631
FG C-050632
PL C-050633
VPO C-050634
14x20 AL C-050641
PL C-050643
VPO C-050644

CAUTION BEWARE OF FALLING OBJECTS

3x5 VPO C-050714
7x10 AL C-050721
FG C-050722
PL C-050723
VPO C-050724
10x14 AL C-050731
FG C-050732
PL C-050733
VPO C-050734
14x20 AL C-050741
PL C-050743
VPO C-050744

CAUTION BUMP HAT REQUIRED

3x5 VPO C-050814
7x10 AL C-050821
FG C-050822
PL C-050823
VPO C-050824
10x14 AL C-050831
FG C-050832
PL C-050833
VPO C-050834
14x20 AL C-050841
PL C-050843
VPO C-050844

CAUTION BURIED GAS LINE

3x5 VPO C-050914
7x10 AL C-050921
FG C-050922
PL C-050923
VPO C-050924
10x14 AL C-050931
FG C-050932
PL C-050933
VPO C-050934
14x20 AL C-050941
PL C-050943
VPO C-050944

CAUTION BURIED WATER LINE

3x5 VPO C-051114
7x10 AL C-051121
FG C-051122
PL C-051123
VPO C-051124
10x14 AL C-051131
FG C-051132
PL C-051133
VPO C-051134
14x20 AL C-051141
PL C-051143
VPO C-051144

CAUTION

3x5 VPO C-080614
7x10 AL C-080621
FG C-080622
PL C-080623
VPO C-080624
10x14 AL C-080631
FG C-080632
PL C-080633
VPO C-080634
14x20 AL C-080641
PL C-080643
VPO C-080644

CAUTION CARBON MONOXIDE MAY BE PRESENT

3x5 VPO C-080214
7x10 AL C-080221
FG C-080222
PL C-080223
VPO C-080224
10x14 AL C-080231
FG C-080232
PL C-080233
VPO C-080234
14x20 AL C-080241
PL C-080243
VPO C-080244

CAUTION CAUSTIC

3x5 VPO C-080314
7x10 AL C-080321
FG C-080322
PL C-080323
VPO C-080324
10x14 AL C-080331
FG C-080332
PL C-080333
VPO C-080334
14x20 AL C-080341
PL C-080343
VPO C-080344

CAUTION CAUSTIC SODA AVOID SKIN OR EYE CONTACT AVOID INHALATION OR INGESTION CAN CAUSE SEVERE BURNS WEAR PROTECTIVE CLOTHING WHEN WORKING WITH CAUSTIC SODA IF SKIN OR EYES ARE CONTACTED FLUSH WITH WATER FOR 15 MIN.

3x5 VPO C-080414
7x10 AL C-080421
FG C-080422
PL C-080423
VPO C-080424
10x14 AL C-080431
FG C-080432
PL C-080433
VPO C-080434
14x20 AL C-080441
PL C-080443
VPO C-080444

CAUTION CHAIN GAS CYLINDERS

3x5 VPO C-080814
7x10 AL C-080821
FG C-080822
PL C-080823
VPO C-080824
10x14 AL C-080831
FG C-080832
PL C-080833
VPO C-080834
14x20 AL C-080841
PL C-080843
VPO C-080844

CAUTION CHEMICAL GOGGLE AREA

3x5 VPO C-080914
7x10 AL C-080921
FG C-080922
PL C-080923
VPO C-080924
10x14 AL C-080931
FG C-080932
PL C-080933
VPO C-080934
14x20 AL C-080941
PL C-080943
VPO C-080944

CAUTION CHEMICALS

3x5 VPO C-081114
7x10 AL C-081121
FG C-081122
PL C-081123
VPO C-081124
10x14 AL C-081131
FG C-081132
PL C-081133
VPO C-081134
14x20 AL C-081141
PL C-081143
VPO C-081144

CAUTION CHLORINE AREA

3x5 VPO C-081214
7x10 AL C-081221
FG C-081222
PL C-081223
VPO C-081224
10x14 AL C-081231
FG C-081232
PL C-081233
VPO C-081234
14x20 AL C-081241
PL C-081243
VPO C-081244

CAUTION CHLORINE AVOID INHALATION AND SKIN OR EYE CONTACT INHALATION WILL CAUSE SHORTNESS OF BREATH AND NAUSEA A NIOSH/MSHA APPROVED CHEMICAL CARTRIDGE TYPE ESCAPE RESPIRATOR SHOULD BE CARRIED AT ALL TIMES WHEN HANDLING CHLORINE

3x5 VPO C-081314
7x10 AL C-081321
FG C-081322
PL C-081323
VPO C-081324
10x14 AL C-081331
FG C-081332
PL C-081333
VPO C-081334
14x20 AL C-081341
PL C-081343
VPO C-081344

CAUTION CLASS II HELIUM NEON LASER DO NOT STARE INTO BEAM

3x5 VPO C-081414
7x10 AL C-081421
FG C-081422
PL C-081423
VPO C-081424
10x14 AL C-081431
FG C-081432
PL C-081433
VPO C-081434
14x20 AL C-081441
PL C-081443
VPO C-081444

CAUTION CLEARANCE ____ FT. ____ IN.

3x5 VPO C-081514
7x10 AL C-081521
FG C-081522
PL C-081523
VPO C-081524
10x14 AL C-081531
FG C-081532
PL C-081533
VPO C-081534
14x20 AL C-081541
PL C-081543
VPO C-081544

CAUTION CLOSE CLEARANCE

3x5 VPO C-081614
7x10 AL C-081621
FG C-081622
PL C-081623
VPO C-081624
10x14 AL C-081631
FG C-081632
PL C-081633
VPO C-081634
14x20 AL C-081641
PL C-081643
VPO C-081644

CAUTION CLOTHING CONTAMINATED WITH LEAD DO NOT REMOVE DUST BY BLOWING

3x5 VPO C-081714
7x10 AL C-081721
FG C-081722
PL C-081723
VPO C-081724
10x14 AL C-081731
FG C-081732
PL C-081733
VPO C-081734
14x20 AL C-081741
PL C-081743
VPO C-081744

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY

10

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!



THE SIGNS OF A SAFE INDUSTRY



CAUTION

CAUTION CLOTHING CONTAMINATED WITH LEAD DO NOT REMOVE DUST BY BLOWING OR SHAKING DISPOSE OF LEAD CONTAMINATED WASH WATER IN ACCORDANCE WITH APPLICABLE LOCAL STATE OR FEDERAL REGULATIONS	CAUTION COMPRESSED AIR	CAUTION CONFINED SPACE	CAUTION CONFINED SPACE DO NOT ENTER WITHOUT OBTAINING PERMIT NO. _____	CAUTION CONFINED SPACE ENTER BY PERMIT ONLY	CAUTION CONFINED SPACE ENTRY PERMIT REQUIRED CALL SECURITY	CAUTION CONFINED SPACE ENTRY PERMIT REQUIRED CONTACT YOUR SUPERVISOR
3x5 VPO C-081814 7x10 AL C-081821 FG C-081822 PL C-081823 VPO C-081824 10x14 AL C-081831 FG C-081832 PL C-081833 VPO C-081834 14x20 AL C-081841 PL C-081843 VPO C-081844	3x5 VPO C-081914 7x10 AL C-081921 FG C-081922 PL C-081923 VPO C-081924 10x14 AL C-081931 FG C-081932 PL C-081933 VPO C-081934 14x20 AL C-081941 PL C-081943 VPO C-081944	3x5 VPO C-082014 7x10 AL C-082021 FG C-082022 PL C-082023 VPO C-082024 10x14 AL C-082031 FG C-082032 PL C-082033 VPO C-082034 14x20 AL C-082041 PL C-082043 VPO C-082044	3x5 VPO C-082214 7x10 AL C-082221 FG C-082222 PL C-082223 VPO C-082224 10x14 AL C-082231 FG C-082232 PL C-082233 VPO C-082234 14x20 AL C-082241 PL C-082243 VPO C-082244	3x5 VPO C-082314 7x10 AL C-082321 FG C-082322 PL C-082323 VPO C-082324 10x14 AL C-082331 FG C-082332 PL C-082333 VPO C-082334 14x20 AL C-082341 PL C-082343 VPO C-082344	3x5 VPO C-082414 7x10 AL C-082421 FG C-082422 PL C-082423 VPO C-082424 10x14 AL C-082431 FG C-082432 PL C-082433 VPO C-082434 14x20 AL C-082441 PL C-082443 VPO C-082444	3x5 VPO C-082514 7x10 AL C-082521 FG C-082522 PL C-082523 VPO C-082524 10x14 AL C-082531 FG C-082532 PL C-082533 VPO C-082534 14x20 AL C-082541 PL C-082543 VPO C-082544
CAUTION CONFINED SPACE NO. _____ ENTRY PERMIT REQUIRED CALL _____	CAUTION CONGESTED AISLE	CAUTION CONGESTED AREA	CAUTION CONNECT GROUND WIRE BEFORE USING	CAUTION CONSTRUCTION AREA	CAUTION CONTAINS ASBESTOS FIBERS AVOID CREATING DUST BREATHING ASBESTOS DUST MAY CAUSE SERIOUS BODILY HARM	CAUTION CONTAINS CORROSIVE LIQUID
3x5 VPO C-082614 7x10 AL C-082621 FG C-082622 PL C-082623 VPO C-082624 10x14 AL C-082631 FG C-082632 PL C-082633 VPO C-082634 14x20 AL C-082641 PL C-082643 VPO C-082644	3x5 VPO C-082714 7x10 AL C-082721 FG C-082722 PL C-082723 VPO C-082724 10x14 AL C-082731 FG C-082732 PL C-082733 VPO C-082734 14x20 AL C-082741 PL C-082743 VPO C-082744	3x5 VPO C-082814 7x10 AL C-082821 FG C-082822 PL C-082823 VPO C-082824 10x14 AL C-082831 FG C-082832 PL C-082833 VPO C-082834 14x20 AL C-082841 PL C-082843 VPO C-082844	3x5 VPO C-082914 7x10 AL C-082921 FG C-082922 PL C-082923 VPO C-082924 10x14 AL C-082931 FG C-082932 PL C-082933 VPO C-082934 14x20 AL C-082941 PL C-082943 VPO C-082944	3x5 VPO C-083014 7x10 AL C-083021 FG C-083022 PL C-083023 VPO C-083024 10x14 AL C-083031 FG C-083032 PL C-083033 VPO C-083034 14x20 AL C-083041 PL C-083043 VPO C-083044	3x5 VPO C-083114 7x10 AL C-083121 FG C-083122 PL C-083123 VPO C-083124 10x14 AL C-083131 FG C-083132 PL C-083133 VPO C-083134 14x20 AL C-083141 PL C-083143 VPO C-083144	3x5 VPO C-083214 7x10 AL C-083221 FG C-083222 PL C-083223 VPO C-083224 10x14 AL C-083231 FG C-083232 PL C-083233 VPO C-083234 14x20 AL C-083241 PL C-083243 VPO C-083244
CAUTION CONTAINS ETHYLENE OXIDE CANCER AND REPRODUCTIVE HAZARD AVOID BREATHING VAPORS	CAUTION CONTAINS HAZARDOUS MATERIAL SEE MSDS FILE	CAUTION CONTAINS PCB CANCER HAZARD	CAUTION CONVEYOR MAY START WITHOUT WARNING	CAUTION CORROSIVE MATERIAL IN USE	CAUTION CUTTING AND WELDING PERMIT REQUIRED IN THIS AREA	CAUTION DEPOSIT MATCHES AND ALL SMOKING MATERIAL IN THIS RECEPTACLE
3x5 VPO C-083314 7x10 AL C-083321 FG C-083322 PL C-083323 VPO C-083324 10x14 AL C-083331 FG C-083332 PL C-083333 VPO C-083334 14x20 AL C-083341 PL C-083343 VPO C-083344	3x5 VPO C-083414 7x10 AL C-083421 FG C-083422 PL C-083423 VPO C-083424 10x14 AL C-083431 FG C-083432 PL C-083433 VPO C-083434 14x20 AL C-083441 PL C-083443 VPO C-083444	3x5 VPO C-083514 7x10 AL C-083521 FG C-083522 PL C-083523 VPO C-083524 10x14 AL C-083531 FG C-083532 PL C-083533 VPO C-083534 14x20 AL C-083541 PL C-083543 VPO C-083544	3x5 VPO C-083614 7x10 AL C-083621 FG C-083622 PL C-083623 VPO C-083624 10x14 AL C-083631 FG C-083632 PL C-083633 VPO C-083634 14x20 AL C-083641 PL C-083643 VPO C-083644	3x5 VPO C-083714 7x10 AL C-083721 FG C-083722 PL C-083723 VPO C-083724 10x14 AL C-083731 FG C-083732 PL C-083733 VPO C-083734 14x20 AL C-083741 PL C-083743 VPO C-083744	3x5 VPO C-083914 7x10 AL C-083921 FG C-083922 PL C-083923 VPO C-083924 10x14 AL C-083931 FG C-083932 PL C-083933 VPO C-083934 14x20 AL C-083941 PL C-083943 VPO C-083944	3x5 VPO C-110114 7x10 AL C-110121 FG C-110122 PL C-110123 VPO C-110124 10x14 AL C-110131 FG C-110132 PL C-110133 VPO C-110134 14x20 AL C-110141 PL C-110143 VPO C-110144
CAUTION DISCONNECT POWER BEFORE SERVICING	CAUTION DO NOT ENTER	CAUTION DO NOT BACK THIS VEHICLE UNLESS YOU ARE SURE IT IS SAFE AND CLEAR	CAUTION DO NOT ENTER THIS SHOP WITHOUT EYE PROTECTION	CAUTION DO NOT ENTER WITHOUT AIR PAC WHEN CHLORINE ALARM IS ON	CAUTION DO NOT ENTER WHEN RED LIGHT IS FLASHING	CAUTION DO NOT ENTER WHILE MACHINERY IN MOTION
3x5 VPO C-110314 7x10 AL C-110321 FG C-110322 PL C-110323 VPO C-110324 10x14 AL C-110331 FG C-110332 PL C-110333 VPO C-110334 14x20 AL C-110341 PL C-110343 VPO C-110344	3x5 VPO C-110414 7x10 AL C-110421 FG C-110422 PL C-110423 VPO C-110424 10x14 AL C-110431 FG C-110432 PL C-110433 VPO C-110434 14x20 AL C-110441 PL C-110443 VPO C-110444	3x5 VPO C-110514 7x10 AL C-110521 FG C-110522 PL C-110523 VPO C-110524 10x14 AL C-110531 FG C-110532 PL C-110533 VPO C-110534 14x20 AL C-110541 PL C-110543 VPO C-110544	3x5 VPO C-110914 7x10 AL C-110921 FG C-110922 PL C-110923 VPO C-110924 10x14 AL C-110931 FG C-110932 PL C-110933 VPO C-110934 14x20 AL C-110941 PL C-110943 VPO C-110944	3x5 VPO C-111014 7x10 AL C-111021 FG C-111022 PL C-111023 VPO C-111024 10x14 AL C-111031 FG C-111032 PL C-111033 VPO C-111034 14x20 AL C-111041 PL C-111043 VPO C-111044	3x5 VPO C-111114 7x10 AL C-111121 FG C-111122 PL C-111123 VPO C-111124 10x14 AL C-111131 FG C-111132 PL C-111133 VPO C-111134 14x20 AL C-111141 PL C-111143 VPO C-111144	3x5 VPO C-111214 7x10 AL C-111221 FG C-111222 PL C-111223 VPO C-111224 10x14 AL C-111231 FG C-111232 PL C-111233 VPO C-111234 14x20 AL C-111241 PL C-111243 VPO C-111244

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!

CAUTION



THE SIGNS OF A SAFE INDUSTRY



CAUTION

DO NOT ENTER
WITHOUT A
CONFINED SPACE
PERMIT

3x5 VPO	C-111514
7x10 AL	C-111521
FG	C-111522
PL	C-111523
VPO	C-111524
10x14 AL	C-111531
FG	C-111532
PL	C-111533
VPO	C-111534
14x20 AL	C-111541
PL	C-111543
VPO	C-111544

CAUTION

DO NOT ENTER
WITHOUT EYE
PROTECTION

3x5 VPO	C-111614
7x10 AL	C-111621
FG	C-111622
PL	C-111623
VPO	C-111624
10x14 AL	C-111631
FG	C-111632
PL	C-111633
VPO	C-111634
14x20 AL	C-111641
PL	C-111643
VPO	C-111644

CAUTION

DO NOT GRIND IF
CLEARANCE BETWEEN
WHEEL AND TOOL REST
IS MORE THAN 1/16 INCH

3x5 VPO	C-111814
7x10 AL	C-111821
FG	C-111822
PL	C-111823
VPO	C-111824
10x14 AL	C-111831
FG	C-111832
PL	C-111833
VPO	C-111834
14x20 AL	C-111841
PL	C-111843
VPO	C-111844

CAUTION

DO NOT GRIND IF
CLEARANCE BETWEEN
WHEEL AND TOOL REST IS
MORE THAN 1/8 INCH

3x5 VPO	C-111914
7x10 AL	C-111921
FG	C-111922
PL	C-111923
VPO	C-111924
10x14 AL	C-111931
FG	C-111932
PL	C-111933
VPO	C-111934
14x20 AL	C-111941
PL	C-111943
VPO	C-111944

CAUTION

DO NOT OPERATE MACHINERY
WITHOUT GUARDS
DO NOT REMOVE GUARDS,
CLEAN, OIL OR REPAIR
MACHINERY
WHILE IN MOTION

3x5 VPO	C-112114
7x10 AL	C-112121
FG	C-112122
PL	C-112123
VPO	C-112124
10x14 AL	C-112131
FG	C-112132
PL	C-112133
VPO	C-112134
14x20 AL	C-112141
PL	C-112143
VPO	C-112144

CAUTION

DO NOT OPERATE
THIS EQUIPMENT
WITHOUT
EAR PROTECTION

3x5 VPO	C-112214
7x10 AL	C-112221
FG	C-112222
PL	C-112223
VPO	C-112224
10x14 AL	C-112231
FG	C-112232
PL	C-112233
VPO	C-112234
14x20 AL	C-112241
PL	C-112243
VPO	C-112244

CAUTION

DO NOT OPERATE
THIS MACHINE
WITHOUT
EYE PROTECTION

3x5 VPO	C-112414
7x10 AL	C-112421
FG	C-112422
PL	C-112423
VPO	C-112424
10x14 AL	C-112431
FG	C-112432
PL	C-112433
VPO	C-112434
14x20 AL	C-112441
PL	C-112443
VPO	C-112444

CAUTION

DO NOT OPERATE
THIS MACHINE
WITHOUT
GUARDS IN PLACE

3x5 VPO	C-112614
7x10 AL	C-112621
FG	C-112622
PL	C-112623
VPO	C-112624
10x14 AL	C-112631
FG	C-112632
PL	C-112633
VPO	C-112634
14x20 AL	C-112641
PL	C-112643
VPO	C-112644

CAUTION

DO NOT
OPERATE
WITHOUT GUARD

3x5 VPO	C-112714
7x10 AL	C-112721
FG	C-112722
PL	C-112723
VPO	C-112724
10x14 AL	C-112731
FG	C-112732
PL	C-112733
VPO	C-112734
14x20 AL	C-112741
PL	C-112743
VPO	C-112744

CAUTION

DO NOT STARE INTO
BEAM HELIUM NEON
LASER

3x5 VPO	C-113014
7x10 AL	C-113021
FG	C-113022
PL	C-113023
VPO	C-113024
10x14 AL	C-113031
FG	C-113032
PL	C-113033
VPO	C-113034
14x20 AL	C-113041
PL	C-113043
VPO	C-113044

CAUTION

DO NOT STARE
INTO BEAM
LASER IN USE

3x5 VPO	C-113114
7x10 AL	C-113121
FG	C-113122
PL	C-113123
VPO	C-113124
10x14 AL	C-113131
FG	C-113132
PL	C-113133
VPO	C-113134
14x20 AL	C-113141
PL	C-113143
VPO	C-113144

CAUTION

DO NOT TALK TO
OPERATOR WHILE
MACHINE IS IN
MOTION

3x5 VPO	C-113214
7x10 AL	C-113221
FG	C-113222
PL	C-113223
VPO	C-113224
10x14 AL	C-113231
FG	C-113232
PL	C-113233
VPO	C-113234
14x20 AL	C-113241
PL	C-113243
VPO	C-113244

CAUTION

DO NOT THROW
MATCHES, RUBBISH,
CIGARETTE OR CIGAR
STUBS IN URINALS

3x5 VPO	C-113314
7x10 AL	C-113321
FG	C-113322
PL	C-113323
VPO	C-113324
10x14 AL	C-113331
FG	C-113332
PL	C-113333
VPO	C-113334
14x20 AL	C-113341
PL	C-113343
VPO	C-113344

CAUTION

DO NOT USE
COMPRESSED AIR
TO BLOW OFF
CLOTHING

3x5 VPO	C-113414
7x10 AL	C-113421
FG	C-113422
PL	C-113423
VPO	C-113424
10x14 AL	C-113431
FG	C-113432
PL	C-113433
VPO	C-113434
14x20 AL	C-113441
PL	C-113443
VPO	C-113444

CAUTION

DO NOT USE
NEAR ELECTRICAL
EQUIPMENT

3x5 VPO	C-113514
7x10 AL	C-113521
FG	C-113522
PL	C-113523
VPO	C-113524
10x14 AL	C-113531
FG	C-113532
PL	C-113533
VPO	C-113534
14x20 AL	C-113541
PL	C-113543
VPO	C-113544

CAUTION

DO NOT USE
ON ELECTRICAL
FIRES

3x5 VPO	C-113614
7x10 AL	C-113621
FG	C-113622
PL	C-113623
VPO	C-113624
10x14 AL	C-113631
FG	C-113632
PL	C-113633
VPO	C-113634
14x20 AL	C-113641
PL	C-113643
VPO	C-113644

CAUTION

DO NOT
WALK ON
CONVEYORS

3x5 VPO	C-113714
7x10 AL	C-113721
FG	C-113722
PL	C-113723
VPO	C-113724
10x14 AL	C-113731
FG	C-113732
PL	C-113733
VPO	C-113734
14x20 AL	C-113741
PL	C-113743
VPO	C-113744

CAUTION

DO NOT WEAR
GLOVES WHILE
OPERATING
THIS MACHINE

3x5 VPO	C-113814
7x10 AL	C-113821
FG	C-113822
PL	C-113823
VPO	C-113824
10x14 AL	C-113831
FG	C-113832
PL	C-113833
VPO	C-113834
14x20 AL	C-113841
PL	C-113843
VPO	C-113844

CAUTION

DOCK
SLIPPERY
WHEN WET

3x5 VPO	C-113914
7x10 AL	C-113921
FG	C-113922
PL	C-113923
VPO	C-113924
10x14 AL	C-113931
FG	C-113932
PL	C-113933
VPO	C-113934
14x20 AL	C-113941
PL	C-113943
VPO	C-113944

CAUTION

DON'T CLEAN, OIL,
OR REPAIR MACHINERY
WHILE IN MOTION

3x5 VPO	C-114014
7x10 AL	C-114021
FG	C-114022
PL	C-114023
VPO	C-114024
10x14 AL	C-114031
FG	C-114032
PL	C-114033
VPO	C-114034
14x20 AL	C-114041
PL	C-114043
VPO	C-114044

CAUTION

DON'T START
OUT OF
ORDER

3x5 VPO	C-114214
7x10 AL	C-114221
FG	C-114222
PL	C-114223
VPO	C-114224
10x14 AL	C-114231
FG	C-114232
PL	C-114233
VPO	C-114234
14x20 AL	C-114241
PL	C-114243
VPO	C-114244

CAUTION

DOOR MAY
CLOSE SUDDENLY
WITHOUT WARNING

3x5 VPO	C-114314
7x10 AL	C-114321
FG	C-114322
PL	C-114323
VPO	C-114324
10x14 AL	C-114331
FG	C-114332
PL	C-114333
VPO	C-114334
14x20 AL	C-114341
PL	C-114343
VPO	C-114344

CAUTION

DOOR OPENS
INWARD

3x5 VPO	C-114514
7x10 AL	C-114521
FG	C-114522
PL	C-114523
VPO	C-114524
10x14 AL	C-114531
FG	C-114532
PL	C-114533
VPO	C-114534
14x20 AL	C-114541
PL	C-114543
VPO	C-114544

CAUTION

DOOR OPENS
OUTWARD

3x5 VPO	C-114414
7x10 AL	C-114421
FG	C-114422
PL	C-114423
VPO	C-114424
10x14 AL	C-114431
FG	C-114432
PL	C-114433
VPO	C-114434
14x20 AL	C-114441
PL	C-114443
VPO	C-114444

CAUTION

EAR AND EYE
PROTECTION
AREA

3x5 VPO	C-160114
7x10 AL	C-160121
FG	C-160122
PL	C-160123
VPO	C-160124
10x14 AL	C-160131
FG	C-160132
PL	C-160133
VPO	C-160134
14x20 AL	C-160141
PL	C-160143
VPO	C-160144

CAUTION

EAR PLUGS
REQUIRED IN
THIS AREA

3x5 VPO	C-161214
7x10 AL	C-161221
FG	C-161222
PL	C-161223
VPO	C-161224
10x14 AL	C-161231
FG	C-161232
PL	C-161233
VPO	C-161234
14x20 AL	C-161241
PL	C-161243
VPO	C-161244

CAUTION

EAR
PROTECTION
AREA

3x5 VPO	C-160214
7x10 AL	C-160221
FG	C-160222
PL	C-160223
VPO	C-160224
10x14 AL	C-160231
FG	C-160232
PL	C-160233
VPO	C-160234
14x20 AL	C-160241
PL	C-160243
VPO	C-160244

CAUTION

EAR PROTECTION
MUST BE WORN
IN THIS AREA

3x5 VPO	C-160414
7x10 AL	C-160421
FG	C-160422
PL	C-160423
VPO	C-160424
10x14 AL	C-160431
FG	C-160432
PL	C-160433
VPO	C-160434
14x20 AL	C-160441
PL	C-160443
VPO	C-160444

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY

THE SIGNS OF A SAFE INDUSTRY

MATERIALS



CAUTION

CAUTION EAR PROTECTION MUST BE WORN WHILE WORKING ON THIS OPERATION 3x5 VPO C-160514 7x10 AL C-160521 FG C-160522 PL C-160523 VPO C-160524 10x14 AL C-160531 FG C-160532 PL C-160533 VPO C-160534 14x20 AL C-160541 PL C-160543 VPO C-160544	CAUTION EAR PROTECTION REQUIRED 3x5 VPO C-160614 7x10 AL C-160621 FG C-160622 PL C-160623 VPO C-160624 10x14 AL C-160631 FG C-160632 PL C-160633 VPO C-160634 14x20 AL C-160641 PL C-160643 VPO C-160644	CAUTION EAR PROTECTION REQUIRED AFTER ____ HRS dbA 3x5 VPO C-160714 7x10 AL C-160721 FG C-160722 PL C-160723 VPO C-160724 10x14 AL C-160731 FG C-160732 PL C-160733 VPO C-160734 14x20 AL C-160741 PL C-160743 VPO C-160744	CAUTION EAR PROTECTION REQUIRED IN THIS AREA 3x5 VPO C-160814 7x10 AL C-160821 FG C-160822 PL C-160823 VPO C-160824 10x14 AL C-160831 FG C-160832 PL C-160833 VPO C-160834 14x20 AL C-160841 PL C-160843 VPO C-160844	CAUTION EAR PROTECTION REQUIRED NOISE LEVEL IS ABOVE 85dba 3x5 VPO C-160914 7x10 AL C-160921 FG C-160922 PL C-160923 VPO C-160924 10x14 AL C-160931 FG C-160932 PL C-160933 VPO C-160934 14x20 AL C-160941 PL C-160943 VPO C-160944	CAUTION EAR PROTECTION REQUIRED WHEN THIS EQUIPMENT IS OPERATING 3x5 VPO C-161114 7x10 AL C-161121 FG C-161122 PL C-161123 VPO C-161124 10x14 AL C-161131 FG C-161132 PL C-161133 VPO C-161134 14x20 AL C-161141 PL C-161143 VPO C-161144	CAUTION ELECTRICAL HAZARD 3x5 VPO C-960214 7x10 AL C-960221 FG C-960222 PL C-960223 VPO C-960224 10x14 AL C-960231 FG C-960232 PL C-960233 VPO C-960234 14x20 AL C-960241 PL C-960243 VPO C-960244
CAUTION ELECTRICAL SHOCK HAZARD 3x5 VPO C-161314 7x10 AL C-161321 FG C-161322 PL C-161323 VPO C-161324 10x14 AL C-161331 FG C-161332 PL C-161333 VPO C-161334 14x20 AL C-161341 PL C-161343 VPO C-161344	CAUTION EMERGENCY STOP 3x5 VPO C-161414 7x10 AL C-161421 FG C-161422 PL C-161423 VPO C-161424 10x14 AL C-161431 FG C-161432 PL C-161433 VPO C-161434 14x20 AL C-161441 PL C-161443 VPO C-161444	CAUTION EMERGENCY STOP BUTTON 3x5 VPO C-960114 7x10 AL C-960121 FG C-960122 PL C-960123 VPO C-960124 10x14 AL C-960131 FG C-960132 PL C-960133 VPO C-960134 14x20 AL C-960141 PL C-960143 VPO C-960144	CAUTION EMPLOYEES ARE NOT PERMITTED TO REMOVE GUARDS OR OPERATE MACHINE WITHOUT THEM 3x5 VPO C-161514 7x10 AL C-161521 FG C-161522 PL C-161523 VPO C-161524 10x14 AL C-161531 FG C-161532 PL C-161533 VPO C-161534 14x20 AL C-161541 PL C-161543 VPO C-161544	CAUTION ENTRY PROHIBITED WITHOUT PERMIT TEST FOR O2 DEFICIENCY, H2S AND COMBUSTIBLE VAPORS 3x5 VPO C-161614 7x10 AL C-161621 FG C-161622 PL C-161623 VPO C-161624 10x14 AL C-161631 FG C-161632 PL C-161633 VPO C-161634 14x20 AL C-161641 PL C-161643 VPO C-161644	CAUTION EQUIPMENT MAY MOVE AUTOMATICALLY WITHOUT WARNING 3x5 VPO C-161714 7x10 AL C-161721 FG C-161722 PL C-161723 VPO C-161724 10x14 AL C-161731 FG C-161732 PL C-161733 VPO C-161734 14x20 AL C-161741 PL C-161743 VPO C-161744	CAUTION EQUIPMENT REMOTELY CONTROLLED 3x5 VPO C-161814 7x10 AL C-161821 FG C-161822 PL C-161823 VPO C-161824 10x14 AL C-161831 FG C-161832 PL C-161833 VPO C-161834 14x20 AL C-161841 PL C-161843 VPO C-161844
CAUTION EQUIPMENT STARTS AUTOMATICALLY 3x5 VPO C-161914 7x10 AL C-161921 FG C-161922 PL C-161923 VPO C-161924 10x14 AL C-161931 FG C-161932 PL C-161933 VPO C-161934 14x20 AL C-161941 PL C-161943 VPO C-161944	CAUTION EYE PROTECTION AND HARD HATS MUST BE WORN IN THIS AREA 3x5 VPO C-162114 7x10 AL C-162121 FG C-162122 PL C-162123 VPO C-162124 10x14 AL C-162131 FG C-162132 PL C-162133 VPO C-162134 14x20 AL C-162141 PL C-162143 VPO C-162144	CAUTION EYE PROTECTION AREA 3x5 VPO C-162214 7x10 AL C-162221 FG C-162222 PL C-162223 VPO C-162224 10x14 AL C-162231 FG C-162232 PL C-162233 VPO C-162234 14x20 AL C-162241 PL C-162243 VPO C-162244	CAUTION EYE PROTECTION AREA CONTACT LENSES NOT ALLOWED 3x5 VPO C-162414 7x10 AL C-162421 FG C-162422 PL C-162423 VPO C-162424 10x14 AL C-162431 FG C-162432 PL C-162433 VPO C-162434 14x20 AL C-162441 PL C-162443 VPO C-162444	CAUTION EYE PROTECTION MUST BE WORN IN THIS AREA 3x5 VPO C-162514 7x10 AL C-162521 FG C-162522 PL C-162523 VPO C-162524 10x14 AL C-162531 FG C-162532 PL C-162533 VPO C-162534 14x20 AL C-162541 PL C-162543 VPO C-162544	CAUTION EYE PROTECTION MUST BE WORN WHEN CLEANING THIS EQUIPMENT 3x5 VPO C-162614 7x10 AL C-162621 FG C-162622 PL C-162623 VPO C-162624 10x14 AL C-162631 FG C-162632 PL C-162633 VPO C-162634 14x20 AL C-162641 PL C-162643 VPO C-162644	CAUTION EYE PROTECTION REQUIRED 3x5 VPO C-162714 7x10 AL C-162721 FG C-162722 PL C-162723 VPO C-162724 10x14 AL C-162731 FG C-162732 PL C-162733 VPO C-162734 14x20 AL C-162741 PL C-162743 VPO C-162744
CAUTION EYE PROTECTION REQUIRED BEYOND THIS POINT 3x5 VPO C-162814 7x10 AL C-162821 FG C-162822 PL C-162823 VPO C-162824 10x14 AL C-162831 FG C-162832 PL C-162833 VPO C-162834 14x20 AL C-162841 PL C-162843 VPO C-162844	CAUTION EYE PROTECTION REQUIRED IN THIS AREA 3x5 VPO C-162914 7x10 AL C-162921 FG C-162922 PL C-162923 VPO C-162924 10x14 AL C-162931 FG C-162932 PL C-162933 VPO C-162934 14x20 AL C-162941 PL C-162943 VPO C-162944	CAUTION EYE PROTECTION REQUIRED WHEN EQUIPMENT IS OPERATING 3x5 VPO C-171514 7x10 AL C-171521 FG C-171522 PL C-171523 VPO C-171524 10x14 AL C-171531 FG C-171532 PL C-171533 VPO C-171534 14x20 AL C-171541 PL C-171543 VPO C-171544	CAUTION EYE PROTECTION REQUIRED WHEN USING COMPRESSED AIR 3x5 VPO C-163114 7x10 AL C-163121 FG C-163122 PL C-163123 VPO C-163124 10x14 AL C-163131 FG C-163132 PL C-163133 VPO C-163134 14x20 AL C-163141 PL C-163143 VPO C-163144	CAUTION EYE PROTECTION REQUIRED WHILE USING THIS MACHINE 3x5 VPO C-163214 7x10 AL C-163221 FG C-163222 PL C-163223 VPO C-163224 10x14 AL C-163231 FG C-163232 PL C-163233 VPO C-163234 14x20 AL C-163241 PL C-163243 VPO C-163244	CAUTION EYE PROTECTION, GLOVES, APRONS MUST BE WORN WHEN HANDLING CHEMICALS 3x5 VPO C-163314 7x10 AL C-163321 FG C-163322 PL C-163323 VPO C-163324 10x14 AL C-163331 FG C-163332 PL C-163333 VPO C-163334 14x20 AL C-163341 PL C-163343 VPO C-163344	CAUTION FACE LADDER WHEN DESCENDING 3x5 VPO C-260114 7x10 AL C-260121 FG C-260122 PL C-260123 VPO C-260124 10x14 AL C-260131 FG C-260132 PL C-260133 VPO C-260134 14x20 AL C-260141 PL C-260143 VPO C-260144

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!

CAUTION



THE SIGNS OF A SAFE INDUSTRY



CAUTION

FACE MASK
MUST BE WORN
IN SPRAY BOOTH

3x5 VPO C-261814
7x10 AL C-261821
FG C-261822
PL C-261823
VPO C-261824
10x14 AL C-261831
FG C-261832
PL C-261833
VPO C-261834
14x20 AL C-261841
PL C-261843
VPO C-261844

CAUTION

FACE SHIELD AND
GLOVES REQUIRED
WHEN USING
THIS EQUIPMENT

3x5 VPO C-260314
7x10 AL C-260321
FG C-260322
PL C-260323
VPO C-260324
10x14 AL C-260331
FG C-260332
PL C-260333
VPO C-260334
14x20 AL C-260341
PL C-260343
VPO C-260344

CAUTION

FACE SHIELD AND
GOGGLES
MUST BE WORN
IN THIS AREA

3x5 VPO C-260414
7x10 AL C-260421
FG C-260422
PL C-260423
VPO C-260424
10x14 AL C-260431
FG C-260432
PL C-260433
VPO C-260434
14x20 AL C-260441
PL C-260443
VPO C-260444

CAUTION

FACE SHIELD AND
GOGGLES MUST BE
WORN WHEN USING
THIS MACHINE

3x5 VPO C-260514
7x10 AL C-260521
FG C-260522
PL C-260523
VPO C-260524
10x14 AL C-260531
FG C-260532
PL C-260533
VPO C-260534
14x20 AL C-260541
PL C-260543
VPO C-260544

CAUTION

FACE
SHIELD
AREA

3x5 VPO C-260614
7x10 AL C-260621
FG C-260622
PL C-260623
VPO C-260624
10x14 AL C-260631
FG C-260632
PL C-260633
VPO C-260634
14x20 AL C-260641
PL C-260643
VPO C-260644

CAUTION

FACE SHIELD APRON
AND RUBBER GLOVES
REQUIRED WHEN
HANDLING BATTERIES
AND ADDING WATER

3x5 VPO C-260714
7x10 AL C-260721
FG C-260722
PL C-260723
VPO C-260724
10x14 AL C-260731
FG C-260732
PL C-260733
VPO C-260734
14x20 AL C-260741
PL C-260743
VPO C-260744

CAUTION

FALL
PROTECTION
REQUIRED

3x5 VPO C-981114
7x10 AL C-981121
FG C-981122
PL C-981123
VPO C-981124
10x14 AL C-981131
FG C-981132
PL C-981133
VPO C-981134
14x20 AL C-981141
PL C-981143
VPO C-981144

CAUTION

FIRE LANE
KEEP CLEAR

3x5 VPO C-260914
7x10 AL C-260921
FG C-260922
PL C-260923
VPO C-260924
10x14 AL C-260931
FG C-260932
PL C-260933
VPO C-260934
14x20 AL C-260941
PL C-260943
VPO C-260944

CAUTION

FLAMMABLE

3x5 VPO C-960414
7x10 AL C-960421
FG C-960422
PL C-960423
VPO C-960424
10x14 AL C-960431
FG C-960432
PL C-960433
VPO C-960434
14x20 AL C-960441
PL C-960443
VPO C-960444

CAUTION

FLAMMABLE
VAPORS

3x5 VPO C-261114
7x10 AL C-261121
FG C-261122
PL C-261123
VPO C-261124
10x14 AL C-261131
FG C-261132
PL C-261133
VPO C-261134
14x20 AL C-261141
PL C-261143
VPO C-261144

CAUTION

FLOOR LOAD
LBS.
PER SQUARE FOOT

3x5 VPO C-261214
7x10 AL C-261221
FG C-261222
PL C-261223
VPO C-261224
10x14 AL C-261231
FG C-261232
PL C-261233
VPO C-261234
14x20 AL C-261241
PL C-261243
VPO C-261244

CAUTION

FOOT PROTECTION
REQUIRED
IN THIS AREA

3x5 VPO C-261314
7x10 AL C-261321
FG C-261322
PL C-261323
VPO C-261324
10x14 AL C-261331
FG C-261332
PL C-261333
VPO C-261334
14x20 AL C-261341
PL C-261343
VPO C-261344

CAUTION

GLOVES AND
GOGGLES REQUIRED
WHEN FILLING TANKS

3x5 VPO C-360114
7x10 AL C-360121
FG C-360122
PL C-360123
VPO C-360124
10x14 AL C-360131
FG C-360132
PL C-360133
VPO C-360134
14x20 AL C-360141
PL C-360143
VPO C-360144

CAUTION

GLOVES AND
GOGGLES POSITIVELY
MUST BE WORN

3x5 VPO C-960514
7x10 AL C-960521
FG C-960522
PL C-960523
VPO C-960524
10x14 AL C-960531
FG C-960532
PL C-960533
VPO C-960534
14x20 AL C-960541
PL C-960543
VPO C-960544

CAUTION

GOGGLES
POSITIVELY
MUST BE WORN

3x5 VPO C-360214
7x10 AL C-360221
FG C-360222
PL C-360223
VPO C-360224
10x14 AL C-360231
FG C-360232
PL C-360233
VPO C-360234
14x20 AL C-360241
PL C-360243
VPO C-360244

CAUTION

GOGGLES POSITIVELY
MUST BE WORN
WHEN OPERATING
THIS MACHINE

3x5 VPO C-360414
7x10 AL C-360421
FG C-360422
PL C-360423
VPO C-360424
10x14 AL C-360431
FG C-360432
PL C-360433
VPO C-360434
14x20 AL C-360441
PL C-360443
VPO C-360444

CAUTION

GROUND ALL
BARRELS

3x5 VPO C-360514
7x10 AL C-360521
FG C-360522
PL C-360523
VPO C-360524
10x14 AL C-360531
FG C-360532
PL C-360533
VPO C-360534
14x20 AL C-360541
PL C-360543
VPO C-360544

CAUTION

GROUND
BARRELS
BEFORE USING

3x5 VPO C-360614
7x10 AL C-360621
FG C-360622
PL C-360623
VPO C-360624
10x14 AL C-360631
FG C-360632
PL C-360633
VPO C-360634
14x20 AL C-360641
PL C-360643
VPO C-360644

CAUTION

H₂S
MAY BE PRESENT
DO NOT ENTER THIS AREA
WITHOUT APPROVED H₂S
DETECTION EQUIPMENT

3x5 VPO C-370114
7x10 AL C-370121
FG C-370122
PL C-370123
VPO C-370124
10x14 AL C-370131
FG C-370132
PL C-370133
VPO C-370134
14x20 AL C-370141
PL C-370143
VPO C-370144

CAUTION

H₂S
POISONOUS GAS
MAY BE PRESENT

3x5 VPO C-370214
7x10 AL C-370221
FG C-370222
PL C-370223
VPO C-370224
10x14 AL C-370231
FG C-370232
PL C-370233
VPO C-370234
14x20 AL C-370241
PL C-370243
VPO C-370244

CAUTION

HARD HAT
AREA

3x5 VPO C-370314
7x10 AL C-370321
FG C-370322
PL C-370323
VPO C-370324
10x14 AL C-370331
FG C-370332
PL C-370333
VPO C-370334
14x20 AL C-370341
PL C-370343
VPO C-370344

CAUTION

HARD HAT
REQUIRED

3x5 VPO C-960314
7x10 AL C-960321
FG C-960322
PL C-960323
VPO C-960324
10x14 AL C-960331
FG C-960332
PL C-960333
VPO C-960334
14x20 AL C-960341
PL C-960343
VPO C-960344

CAUTION

HARD HATS AND
EYE PROTECTION
MUST BE WORN
IN THIS AREA

3x5 VPO C-370514
7x10 AL C-370521
FG C-370522
PL C-370523
VPO C-370524
10x14 AL C-370531
FG C-370532
PL C-370533
VPO C-370534
14x20 AL C-370541
PL C-370543
VPO C-370544

CAUTION

HARD HATS AND
EYE PROTECTION
REQUIRED

3x5 VPO C-370614
7x10 AL C-370621
FG C-370622
PL C-370623
VPO C-370624
10x14 AL C-370631
FG C-370632
PL C-370633
VPO C-370634
14x20 AL C-370641
PL C-370643
VPO C-370644

CAUTION

HARD HATS
MUST BE WORN
IN THIS AREA

3x5 VPO C-370714
7x10 AL C-370721
FG C-370722
PL C-370723
VPO C-370724
10x14 AL C-370731
FG C-370732
PL C-370733
VPO C-370734
14x20 AL C-370741
PL C-370743
VPO C-370744

CAUTION

HARD HATS
REQUIRED

3x5 VPO C-370814
7x10 AL C-370821
FG C-370822
PL C-370823
VPO C-370824
10x14 AL C-370831
FG C-370832
PL C-370833
VPO C-370834
14x20 AL C-370841
PL C-370843
VPO C-370844

CAUTION

HARD HATS
REQUIRED
IN THIS AREA

3x5 VPO C-960614
7x10 AL C-960621
FG C-960622
PL C-960623
VPO C-960624
10x14 AL C-960631
FG C-960632
PL C-960633
VPO C-960634
14x20 AL C-960641
PL C-960643
VPO C-960644

CAUTION

HARD HATS,
EYE PROTECTION,
EAR PROTECTION
MUST BE WORN
BEYOND THIS POINT

3x5 VPO C-371014
7x10 AL C-371021
FG C-371022
PL C-371023
VPO C-371024
10x14 AL C-371031
FG C-371032
PL C-371033
VPO C-371034
14x20 AL C-371041
PL C-371043
VPO C-371044

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY



CAUTION
HAZARDOUS
CHEMICALS

3x5 VPO C-960714
7x10 AL C-960721
FG C-960722
PL C-960723
VPO C-960724
10x14 AL C-960731
FG C-960732
PL C-960733
VPO C-960734
14x20 AL C-960741
PL C-960743
VPO C-960744

CAUTION
HAZARDOUS
CHEMICALS
STORED
IN THIS AREA

3x5 VPO C-371114
7x10 AL C-371121
FG C-371122
PL C-371123
VPO C-371124
10x14 AL C-371131
FG C-371132
PL C-371133
VPO C-371134
14x20 AL C-371141
PL C-371143
VPO C-371144

CAUTION
HAZARDOUS
MATERIALS

3x5 VPO C-960814
7x10 AL C-960821
FG C-960822
PL C-960823
VPO C-960824
10x14 AL C-960831
FG C-960832
PL C-960833
VPO C-960834
14x20 AL C-960841
PL C-960843
VPO C-960844

CAUTION
HAZARDOUS MATERIALS
STORAGE AREA
UNAUTHORIZED PERSONS
KEEP OUT

3x5 VPO C-371214
7x10 AL C-371221
FG C-371222
PL C-371223
VPO C-371224
10x14 AL C-371231
FG C-371232
PL C-371233
VPO C-371234
14x20 AL C-371241
PL C-371243
VPO C-371244

CAUTION
HAZARDOUS
MATERIALS
STORED
IN THIS AREA

3x5 VPO C-960914
7x10 AL C-960921
FG C-960922
PL C-960923
VPO C-960924
10x14 AL C-960931
FG C-960932
PL C-960933
VPO C-960934
14x20 AL C-960941
PL C-960943
VPO C-960944

CAUTION
HAZARDOUS NOISE AREA
HEARING PROTECTION
REQUIRED

3x5 VPO C-371514
7x10 AL C-371521
FG C-371522
PL C-371523
VPO C-371524
10x14 AL C-371531
FG C-371532
PL C-371533
VPO C-371534
14x20 AL C-371541
PL C-371543
VPO C-371544

CAUTION
HAZARDOUS
WASTE

3x5 VPO C-961014
7x10 AL C-961021
FG C-961022
PL C-961023
VPO C-961024
10x14 AL C-961031
FG C-961032
PL C-961033
VPO C-961034
14x20 AL C-961041
PL C-961043
VPO C-961044

CAUTION
HAZARDOUS WASTE MATERIAL
STORAGE ONLY NO SMOKING,
OPEN FLAMES OR OPEN
LIGHTS IN THIS AREA
UNAUTHORIZED PERSONS
KEEP OUT

3x5 VPO C-371614
7x10 AL C-371621
FG C-371622
PL C-371623
VPO C-371624
10x14 AL C-371631
FG C-371632
PL C-371633
VPO C-371634
14x20 AL C-371641
PL C-371643
VPO C-371644

CAUTION
HEARING PROTECTION
MUST BE WORN
WHILE WORKING
IN THIS AREA

3x5 VPO C-371814
7x10 AL C-371821
FG C-371822
PL C-371823
VPO C-371824
10x14 AL C-371831
FG C-371832
PL C-371833
VPO C-371834
14x20 AL C-371841
PL C-371843
VPO C-371844

CAUTION
HEARING PROTECTION
REQUIRED
IN THIS AREA

3x5 VPO C-961714
7x10 AL C-961721
FG C-961722
PL C-961723
VPO C-961724
10x14 AL C-961731
FG C-961732
PL C-961733
VPO C-961734
14x20 AL C-961741
PL C-961743
VPO C-961744

CAUTION
HIGH NOISE AREA
HEARING PROTECTION
MAY BE REQUIRED

3x5 VPO C-372014
7x10 AL C-372021
FG C-372022
PL C-372023
VPO C-372024
10x14 AL C-372031
FG C-372032
PL C-372033
VPO C-372034
14x20 AL C-372041
PL C-372043
VPO C-372044

CAUTION
HIGH
PRESSURE

3x5 VPO C-372114
7x10 AL C-372121
FG C-372122
PL C-372123
VPO C-372124
10x14 AL C-372131
FG C-372132
PL C-372133
VPO C-372134
14x20 AL C-372141
PL C-372143
VPO C-372144

CAUTION
HIGH VOLTAGE
POWER CABLES IF
OPENED OR DAMAGED
CALL

3x5 VPO C-372214
7x10 AL C-372221
FG C-372222
PL C-372223
VPO C-372224
10x14 AL C-372231
FG C-372232
PL C-372233
VPO C-372234
14x20 AL C-372241
PL C-372243
VPO C-372244

CAUTION
HOT

3x5 VPO C-372314
7x10 AL C-372321
FG C-372322
PL C-372323
VPO C-372324
10x14 AL C-372331
FG C-372332
PL C-372333
VPO C-372334
14x20 AL C-372341
PL C-372343
VPO C-372344

CAUTION
HOT
DO NOT TOUCH

3x5 VPO C-372414
7x10 AL C-372421
FG C-372422
PL C-372423
VPO C-372424
10x14 AL C-372431
FG C-372432
PL C-372433
VPO C-372434
14x20 AL C-372441
PL C-372443
VPO C-372444

CAUTION
HOT
VAPORS

3x5 VPO C-372514
7x10 AL C-372521
FG C-372522
PL C-372523
VPO C-372524
10x14 AL C-372531
FG C-372532
PL C-372533
VPO C-372534
14x20 AL C-372541
PL C-372543
VPO C-372544

CAUTION
HYDROGEN
NO SMOKING
OR OPEN FLAME

3x5 VPO C-372614
7x10 AL C-372621
FG C-372622
PL C-372623
VPO C-372624
10x14 AL C-372631
FG C-372632
PL C-372633
VPO C-372634
14x20 AL C-372641
PL C-372643
VPO C-372644

CAUTION
ICY
CONDITIONS

3x5 VPO C-420114
7x10 AL C-420121
FG C-420122
PL C-420123
VPO C-420124
10x14 AL C-420131
FG C-420132
PL C-420133
VPO C-420134
14x20 AL C-420141
PL C-420143
VPO C-420144

CAUTION
INSPECT
SLINGS
BEFORE USE

3x5 VPO C-420314
7x10 AL C-420321
FG C-420322
PL C-420323
VPO C-420324
10x14 AL C-420331
FG C-420332
PL C-420333
VPO C-420334
14x20 AL C-420341
PL C-420343
VPO C-420344

CAUTION
KEEP
AISLES CLEAR

3x5 VPO C-440214
7x10 AL C-440221
FG C-440222
PL C-440223
VPO C-440224
10x14 AL C-440231
FG C-440232
PL C-440233
VPO C-440234
14x20 AL C-440241
PL C-440243
VPO C-440244

CAUTION
INSPECT
SLINGS
BEFORE USING

3x5 VPO C-441414
7x10 AL C-441421
FG C-441422
PL C-441423
VPO C-441424
10x14 AL C-441431
FG C-441432
PL C-441433
VPO C-441434
14x20 AL C-441441
PL C-441443
VPO C-441444

CAUTION
KEEP ALL TRASH
PICKED UP AND
PLACED IN
THIS RECEPTACLE

3x5 VPO C-440414
7x10 AL C-440421
FG C-440422
PL C-440423
VPO C-440424
10x14 AL C-440431
FG C-440432
PL C-440433
VPO C-440434
14x20 AL C-440441
PL C-440443
VPO C-440444

CAUTION
KEEP CLEAR
WHEN BOOM
IS NEAR
HIGH VOLTAGE

3x5 VPO C-440514
7x10 AL C-440521
FG C-440522
PL C-440523
VPO C-440524
10x14 AL C-440531
FG C-440532
PL C-440533
VPO C-440534
14x20 AL C-440541
PL C-440543
VPO C-440544

CAUTION
KEEP
CLOSED

3x5 VPO C-440614
7x10 AL C-440621
FG C-440622
PL C-440623
VPO C-440624
10x14 AL C-440631
FG C-440632
PL C-440633
VPO C-440634
14x20 AL C-440641
PL C-440643
VPO C-440644

CAUTION
KEEP HANDS
AND
FINGERS AWAY

3x5 VPO C-440714
7x10 AL C-440721
FG C-440722
PL C-440723
VPO C-440724
10x14 AL C-440731
FG C-440732
PL C-440733
VPO C-440734
14x20 AL C-440741
PL C-440743
VPO C-440744

CAUTION
KEEP HANDS
CLEAR WHEN
MACHINE
IS OPERATING

3x5 VPO C-440814
7x10 AL C-440821
FG C-440822
PL C-440823
VPO C-440824
10x14 AL C-440831
FG C-440832
PL C-440833
VPO C-440834
14x20 AL C-440841
PL C-440843
VPO C-440844

CAUTION
KEEP HANDS
OUT OF
MACHINE

3x5 VPO C-440914
7x10 AL C-440921
FG C-440922
PL C-440923
VPO C-440924
10x14 AL C-440931
FG C-440932
PL C-440933
VPO C-440934
14x20 AL C-440941
PL C-440943
VPO C-440944

CAUTION
KEEP
AWAY

3x5 VPO C-961114
7x10 AL C-961121
FG C-961122
PL C-961123
VPO C-961124
10x14 AL C-961131
FG C-961132
PL C-961133
VPO C-961134
14x20 AL C-961141
PL C-961143
VPO C-961144

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!

CAUTION



THE SIGNS OF A SAFE INDUSTRY



CAUTION

KEEP OUT

3x5 VPO C-441114
7x10 AL C-441121
FG C-441122
PL C-441123
VPO C-441124
10x14 AL C-441131
FG C-441132
PL C-441133
VPO C-441134
14x20 AL C-441141
PL C-441143
VPO C-441144

CAUTION

KEEP OUT FROM UNDER CRANE LOADS

3x5 VPO C-441214
7x10 AL C-441221
FG C-441222
PL C-441223
VPO C-441224
10x14 AL C-441231
FG C-441232
PL C-441233
VPO C-441234
14x20 AL C-441241
PL C-441243
VPO C-441244

CAUTION

KEEP SAFETY CHAINS IN PLACE

3x5 VPO C-441314
7x10 AL C-441321
FG C-441322
PL C-441323
VPO C-441324
10x14 AL C-441331
FG C-441332
PL C-441333
VPO C-441334
14x20 AL C-441341
PL C-441343
VPO C-441344

CAUTION

 **LASER AREA**

3x5 VPO C-450114
7x10 AL C-450121
FG C-450122
PL C-450123
VPO C-450124
10x14 AL C-450131
FG C-450132
PL C-450133
VPO C-450134
14x20 AL C-450141
PL C-450143
VPO C-450144

CAUTION

LASER DO NOT STARE INTO BEAM

3x5 VPO C-450214
7x10 AL C-450221
FG C-450222
PL C-450223
VPO C-450224
10x14 AL C-450231
FG C-450232
PL C-450233
VPO C-450234
14x20 AL C-450241
PL C-450243
VPO C-450244

CAUTION

LASER RADIATION DO NOT STARE INTO BEAM CLASS II LASER PRODUCT

3x5 VPO C-450314
7x10 AL C-450321
FG C-450322
PL C-450323
VPO C-450324
10x14 AL C-450331
FG C-450332
PL C-450333
VPO C-450334
14x20 AL C-450341
PL C-450343
VPO C-450344

CAUTION

LASER RADIATION DO NOT STARE INTO BEAM OR VIEW DIRECTLY WITH OPTICAL INSTRUMENTS CLASS IIIa LASER PRODUCT

3x5 VPO C-450414
7x10 AL C-450421
FG C-450422
PL C-450423
VPO C-450424
10x14 AL C-450431
FG C-450432
PL C-450433
VPO C-450434
14x20 AL C-450441
PL C-450443
VPO C-450444

CAUTION

LEAD HAZARD AREA WEAR RESPIRATOR POSSESSION OR USE OF TOBACCO PRODUCTS IS PROHIBITED

3x5 VPO C-450514
7x10 AL C-450521
FG C-450522
PL C-450523
VPO C-450524
10x14 AL C-450531
FG C-450532
PL C-450533
VPO C-450534
14x20 AL C-450541
PL C-450543
VPO C-450544

CAUTION

LEAD WORK AREA

3x5 VPO C-450614
7x10 AL C-450621
FG C-450622
PL C-450623
VPO C-450624
10x14 AL C-450631
FG C-450632
PL C-450633
VPO C-450634
14x20 AL C-450641
PL C-450643
VPO C-450644

CAUTION

LIFELINE MUST BE HOOKED UP WHILE ON PLATFORM

3x5 VPO C-450714
7x10 AL C-450721
FG C-450722
PL C-450723
VPO C-450724
10x14 AL C-450731
FG C-450732
PL C-450733
VPO C-450734
14x20 AL C-450741
PL C-450743
VPO C-450744

CAUTION

LIFT TRUCKS GO SLOW

3x5 VPO C-450814
7x10 AL C-450821
FG C-450822
PL C-450823
VPO C-450824
10x14 AL C-450831
FG C-450832
PL C-450833
VPO C-450834
14x20 AL C-450841
PL C-450843
VPO C-450844

CAUTION

LIQUID NITROGEN GLOVES AND FACE SHIELD REQUIRED

3x5 VPO C-450914
7x10 AL C-450921
FG C-450922
PL C-450923
VPO C-450924
10x14 AL C-450931
FG C-450932
PL C-450933
VPO C-450934
14x20 AL C-450941
PL C-450943
VPO C-450944

CAUTION

LOAD CAPACITY _____ LBS.

3x5 VPO C-451014
7x10 AL C-451021
FG C-451022
PL C-451023
VPO C-451024
10x14 AL C-451031
FG C-451032
PL C-451033
VPO C-451034
14x20 AL C-451041
PL C-451043
VPO C-451044

CAUTION

LOAD CAPACITY _____ TONS

3x5 VPO C-451114
7x10 AL C-451121
FG C-451122
PL C-451123
VPO C-451124
10x14 AL C-451131
FG C-451132
PL C-451133
VPO C-451134
14x20 AL C-451141
PL C-451143
VPO C-451144

CAUTION

LOCK OUT REQUIRED BEFORE ENTERING

3x5 VPO C-451214
7x10 AL C-451221
FG C-451222
PL C-451223
VPO C-451224
10x14 AL C-451231
FG C-451232
PL C-451233
VPO C-451234
14x20 AL C-451241
PL C-451243
VPO C-451244

CAUTION

LOOK BOTH WAYS BEFORE CROSSING

3x5 VPO C-451314
7x10 AL C-451321
FG C-451322
PL C-451323
VPO C-451324
10x14 AL C-451331
FG C-451332
PL C-451333
VPO C-451334
14x20 AL C-451341
PL C-451343
VPO C-451344

CAUTION

LOOK BOTH WAYS BEFORE ENTERING

3x5 VPO C-451414
7x10 AL C-451421
FG C-451422
PL C-451423
VPO C-451424
10x14 AL C-451431
FG C-451432
PL C-451433
VPO C-451434
14x20 AL C-451441
PL C-451443
VPO C-451444

CAUTION

LOOK OUT FOR OVERHEAD CRANES

3x5 VPO C-451514
7x10 AL C-451521
FG C-451522
PL C-451523
VPO C-451524
10x14 AL C-451531
FG C-451532
PL C-451533
VPO C-451534
14x20 AL C-451541
PL C-451543
VPO C-451544

CAUTION

LOW CLEARANCE

3x5 VPO C-452114
7x10 AL C-452121
FG C-452122
PL C-452123
VPO C-452124
10x14 AL C-452131
FG C-452132
PL C-452133
VPO C-452134
14x20 AL C-452141
PL C-452143
VPO C-452144

CAUTION

LOW CLEARANCE AHEAD

3x5 VPO C-451614
7x10 AL C-451621
FG C-451622
PL C-451623
VPO C-451624
10x14 AL C-451631
FG C-451632
PL C-451633
VPO C-451634
14x20 AL C-451641
PL C-451643
VPO C-451644

CAUTION

LOW HEAD CLEARANCE

3x5 VPO C-451714
7x10 AL C-451721
FG C-451722
PL C-451723
VPO C-451724
10x14 AL C-451731
FG C-451732
PL C-451733
VPO C-451734
14x20 AL C-451741
PL C-451743
VPO C-451744

CAUTION

LOW HEAD ROOM

3x5 VPO C-451814
7x10 AL C-451821
FG C-451822
PL C-451823
VPO C-451824
10x14 AL C-451831
FG C-451832
PL C-451833
VPO C-451834
14x20 AL C-451841
PL C-451843
VPO C-451844

CAUTION

LOW OVERHEAD CLEARANCE

3x5 VPO C-980314
7x10 AL C-980321
FG C-980322
PL C-980323
VPO C-980324
10x14 AL C-980331
FG C-980332
PL C-980333
VPO C-980334
14x20 AL C-980341
PL C-980343
VPO C-980344

CAUTION

LOW-HAZARD CONFINED SPACE PERMIT REQUIRED

3x5 VPO C-452214
7x10 AL C-452221
FG C-452222
PL C-452223
VPO C-452224
10x14 AL C-452231
FG C-452232
PL C-452233
VPO C-452234
14x20 AL C-452241
PL C-452243
VPO C-452244

CAUTION

LUBE OIL

3x5 VPO C-451914
7x10 AL C-451921
FG C-451922
PL C-451923
VPO C-451924
10x14 AL C-451931
FG C-451932
PL C-451933
VPO C-451934
14x20 AL C-451941
PL C-451943
VPO C-451944

CAUTION

LUNCH ROOM EQUIPPED WITH MICROWAVE OVENS WHICH COULD BE HARMFUL TO PERSONS WEARING PACEMAKERS

3x5 VPO C-452014
7x10 AL C-452021
FG C-452022
PL C-452023
VPO C-452024
10x14 AL C-452031
FG C-452032
PL C-452033
VPO C-452034
14x20 AL C-452041
PL C-452043
VPO C-452044

CAUTION

MACHINE STARTS AUTOMATICALLY

3x5 VPO C-460114
7x10 AL C-460121
FG C-460122
PL C-460123
VPO C-460124
10x14 AL C-460131
FG C-460132
PL C-460133
VPO C-460134
14x20 AL C-460141
PL C-460143
VPO C-460144

CAUTION

MACHINERY MUST BE STOPPED FOR REPAIRS

3x5 VPO C-460214
7x10 AL C-460221
FG C-460222
PL C-460223
VPO C-460224
10x14 AL C-460231
FG C-460232
PL C-460233
VPO C-460234
14x20 AL C-460241
PL C-460243
VPO C-460244

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY

THE SIGNS OF A SAFE INDUSTRY

MATERIALS



CAUTION

CAUTION MAXIMUM FLOOR LOADING LBS./SQ. FT. 3x5 VPO C-460314 7x10 AL C-460321 FG C-460322 PL C-460323 VPO C-460324 10x14 AL C-460331 FG C-460332 PL C-460333 VPO C-460334 14x20 AL C-460341 PL C-460343 VPO C-460344	CAUTION MAY BE CONTAMINATED WITH PESTICIDE 3x5 VPO C-460414 7x10 AL C-460421 FG C-460422 PL C-460423 VPO C-460424 10x14 AL C-460431 FG C-460432 PL C-460433 VPO C-460434 14x20 AL C-460441 PL C-460443 VPO C-460444	CAUTION MAY BE ICE ON STEPS DURING INCLEMENT WEATHER 3x5 VPO C-460514 7x10 AL C-460521 FG C-460522 PL C-460523 VPO C-460524 10x14 AL C-460531 FG C-460532 PL C-460533 VPO C-460534 14x20 AL C-460541 PL C-460543 VPO C-460544	CAUTION MEN WORKING 3x5 VPO C-460614 7x10 AL C-460621 FG C-460622 PL C-460623 VPO C-460624 10x14 AL C-460631 FG C-460632 PL C-460633 VPO C-460634 14x20 AL C-460641 PL C-460643 VPO C-460644	CAUTION MEN WORKING ↑ ABOVE ↓ 3x5 VPO C-961214 7x10 AL C-961221 FG C-961222 PL C-961223 VPO C-961224 10x14 AL C-961231 FG C-961232 PL C-961233 VPO C-961234 14x20 AL C-961241 PL C-961243 VPO C-961244	CAUTION MEN WORKING OVERHEAD 3x5 VPO C-961314 7x10 AL C-961321 FG C-961322 PL C-961323 VPO C-961324 10x14 AL C-961331 FG C-961332 PL C-961333 VPO C-961334 14x20 AL C-961341 PL C-961343 VPO C-961344	CAUTION MICROWAVE OVEN COULD BE HARMFUL TO PERSONS WEARING PACEMAKERS 3x5 VPO C-460814 7x10 AL C-460821 FG C-460822 PL C-460823 VPO C-460824 10x14 AL C-460831 FG C-460832 PL C-460833 VPO C-460834 14x20 AL C-460841 PL C-460843 VPO C-460844
CAUTION MICROWAVE OVEN IN USE 3x5 VPO C-980214 7x10 AL C-980221 FG C-980222 PL C-980223 VPO C-980224 10x14 AL C-980231 FG C-980232 PL C-980233 VPO C-980234 14x20 AL C-980241 PL C-980243 VPO C-980244	CAUTION MOLTEN METAL 3x5 VPO C-460914 7x10 AL C-460921 FG C-460922 PL C-460923 VPO C-460924 10x14 AL C-460931 FG C-460932 PL C-460933 VPO C-460934 14x20 AL C-460941 PL C-460943 VPO C-460944	CAUTION MOVING CARS 3x5 VPO C-461014 7x10 AL C-461021 FG C-461022 PL C-461023 VPO C-461024 10x14 AL C-461031 FG C-461032 PL C-461033 VPO C-461034 14x20 AL C-461041 PL C-461043 VPO C-461044	CAUTION MOVING EQUIPMENT 3x5 VPO C-461114 7x10 AL C-461121 FG C-461122 PL C-461123 VPO C-461124 10x14 AL C-461131 FG C-461132 PL C-461133 VPO C-461134 14x20 AL C-461141 PL C-461143 VPO C-461144	CAUTION MOVING EQUIPMENT OVERHEAD 3x5 VPO C-461214 7x10 AL C-461221 FG C-461222 PL C-461223 VPO C-461224 10x14 AL C-461231 FG C-461232 PL C-461233 VPO C-461234 14x20 AL C-461241 PL C-461243 VPO C-461244	CAUTION NITROGEN DO NOT ENTER 3x5 VPO C-470114 7x10 AL C-470121 FG C-470122 PL C-470123 VPO C-470124 10x14 AL C-470131 FG C-470132 PL C-470133 VPO C-470134 14x20 AL C-470141 PL C-470143 VPO C-470144	CAUTION NO CONTACT LENSES IN THIS AREA 3x5 VPO C-470214 7x10 AL C-470221 FG C-470222 PL C-470223 VPO C-470224 10x14 AL C-470231 FG C-470232 PL C-470233 VPO C-470234 14x20 AL C-470241 PL C-470243 VPO C-470244
CAUTION NO HEAD ROOM 3x5 VPO C-470314 7x10 AL C-470321 FG C-470322 PL C-470323 VPO C-470324 10x14 AL C-470331 FG C-470332 PL C-470333 VPO C-470334 14x20 AL C-470341 PL C-470343 VPO C-470344	CAUTION NO LIFT TRUCKS ALLOWED BEYOND THIS POINT 3x5 VPO C-470414 7x10 AL C-470421 FG C-470422 PL C-470423 VPO C-470424 10x14 AL C-470431 FG C-470432 PL C-470433 VPO C-470434 14x20 AL C-470441 PL C-470443 VPO C-470444	CAUTION NO SMOKING 3x5 VPO C-470614 7x10 AL C-470621 FG C-470622 PL C-470623 VPO C-470624 10x14 AL C-470631 FG C-470632 PL C-470633 VPO C-470634 14x20 AL C-470641 PL C-470643 VPO C-470644	CAUTION NO SMOKING BEYOND THIS POINT 3x5 VPO C-470714 7x10 AL C-470721 FG C-470722 PL C-470723 VPO C-470724 10x14 AL C-470731 FG C-470732 PL C-470733 VPO C-470734 14x20 AL C-470741 PL C-470743 VPO C-470744	CAUTION NO SMOKING IN THIS AREA 3x5 VPO C-961414 7x10 AL C-961421 FG C-961422 PL C-961423 VPO C-961424 10x14 AL C-961431 FG C-961432 PL C-961433 VPO C-961434 14x20 AL C-961441 PL C-961443 VPO C-961444	CAUTION NO SMOKING ON LOADING DOCKS OR IN TRUCKS 3x5 VPO C-470814 7x10 AL C-470821 FG C-470822 PL C-470823 VPO C-470824 10x14 AL C-470831 FG C-470832 PL C-470833 VPO C-470834 14x20 AL C-470841 PL C-470843 VPO C-470844	CAUTION NO SMOKING WITHIN 50 FEET 3x5 VPO C-470914 7x10 AL C-470921 FG C-470922 PL C-470923 VPO C-470924 10x14 AL C-470931 FG C-470932 PL C-470933 VPO C-470934 14x20 AL C-470941 PL C-470943 VPO C-470944
CAUTION NO THOROUGHFARE 3x5 VPO C-471014 7x10 AL C-471021 FG C-471022 PL C-471023 VPO C-471024 10x14 AL C-471031 FG C-471032 PL C-471033 VPO C-471034 14x20 AL C-471041 PL C-471043 VPO C-471044	CAUTION NO UNAUTHORIZED LOADING OR UNLOADING OF TRUCKS BEYOND THIS POINT 3x5 VPO C-471114 7x10 AL C-471121 FG C-471122 PL C-471123 VPO C-471124 10x14 AL C-471131 FG C-471132 PL C-471133 VPO C-471134 14x20 AL C-471141 PL C-471143 VPO C-471144	CAUTION NOISE AREA EAR PROTECTION REQUIRED AFTER ____ HRS. EXPOSURE 3x5 VPO C-471214 7x10 AL C-471221 FG C-471222 PL C-471223 VPO C-471224 10x14 AL C-471231 FG C-471232 PL C-471233 VPO C-471234 14x20 AL C-471241 PL C-471243 VPO C-471244	CAUTION NOISE HAZARD AREA WEAR EAR PROTECTION WHEN WORKING IN THIS AREA ____ HOURS OR MORE 3x5 VPO C-471314 7x10 AL C-471321 FG C-471322 PL C-471323 VPO C-471324 10x14 AL C-471331 FG C-471332 PL C-471333 VPO C-471334 14x20 AL C-471341 PL C-471343 VPO C-471344	CAUTION NOISE LEVEL GREATER THAN 85dbA EAR PROTECTION REQUIRED 3x5 VPO C-471414 7x10 AL C-471421 FG C-471422 PL C-471423 VPO C-471424 10x14 AL C-471431 FG C-471432 PL C-471433 VPO C-471434 14x20 AL C-471441 PL C-471443 VPO C-471444	CAUTION NON-POTABLE WATER DO NOT DRINK 3x5 VPO C-471614 7x10 AL C-471621 FG C-471622 PL C-471623 VPO C-471624 10x14 AL C-471631 FG C-471632 PL C-471633 VPO C-471634 14x20 AL C-471641 PL C-471643 VPO C-471644	CAUTION NOTICE TO TRUCKERS OPEN REAR DOORS BEFORE BACKING INTO DOCK PLATE 3x5 VPO C-471814 7x10 AL C-471821 FG C-471822 PL C-471823 VPO C-471824 10x14 AL C-471831 FG C-471832 PL C-471833 VPO C-471834 14x20 AL C-471841 PL C-471843 VPO C-471844

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!

CAUTION



THE SIGNS OF A SAFE INDUSTRY



CAUTION OPEN DITCH

3x5 VPO C-570414
7x10 AL C-570421
FG C-570422
PL C-570423
VPO C-570424
10x14 AL C-570431
FG C-570432
PL C-570433
VPO C-570434
14x20 AL C-570441
PL C-570443
VPO C-570444

CAUTION OPEN DOOR SLOWLY

3x5 VPO C-570514
7x10 AL C-570521
FG C-570522
PL C-570523
VPO C-570524
10x14 AL C-570531
FG C-570532
PL C-570533
VPO C-570534
14x20 AL C-570541
PL C-570543
VPO C-570544

CAUTION OPEN FLAME

3x5 VPO C-570614
7x10 AL C-570621
FG C-570622
PL C-570623
VPO C-570624
10x14 AL C-570631
FG C-570632
PL C-570633
VPO C-570634
14x20 AL C-570641
PL C-570643
VPO C-570644

CAUTION OVERHEAD CONVEYOR

3x5 VPO C-570714
7x10 AL C-570721
FG C-570722
PL C-570723
VPO C-570724
10x14 AL C-570731
FG C-570732
PL C-570733
VPO C-570734
14x20 AL C-570741
PL C-570743
VPO C-570744

CAUTION OVERHEAD ELECTRICAL LINES

3x5 VPO C-570814
7x10 AL C-570821
FG C-570822
PL C-570823
VPO C-570824
10x14 AL C-570831
FG C-570832
PL C-570833
VPO C-570834
14x20 AL C-570841
PL C-570843
VPO C-570844

CAUTION PEDESTRIAN CROSSING

3x5 VPO C-600314
7x10 AL C-600321
FG C-600322
PL C-600323
VPO C-600324
10x14 AL C-600331
FG C-600332
PL C-600333
VPO C-600334
14x20 AL C-600341
PL C-600343
VPO C-600344

CAUTION PERSONAL PROTECTIVE CLOTHING IS TO BE WORN AT ALL TIMES WHEN HANDLING CHEMICALS

3x5 VPO C-600414
7x10 AL C-600421
FG C-600422
PL C-600423
VPO C-600424
10x14 AL C-600431
FG C-600432
PL C-600433
VPO C-600434
14x20 AL C-600441
PL C-600443
VPO C-600444

CAUTION PERSONAL PROTECTIVE EQUIPMENT REQUIRED BEYOND THIS POINT

3x5 VPO C-600514
7x10 AL C-600521
FG C-600522
PL C-600523
VPO C-600524
10x14 AL C-600531
FG C-600532
PL C-600533
VPO C-600534
14x20 AL C-600541
PL C-600543
VPO C-600544

CAUTION PERSONS WEARING PACEMAKERS MICROWAVE OVEN IN USE

3x5 VPO C-600814
7x10 AL C-600821
FG C-600822
PL C-600823
VPO C-600824
10x14 AL C-600831
FG C-600832
PL C-600833
VPO C-600834
14x20 AL C-600841
PL C-600843
VPO C-600844

CAUTION PINCH POINT

3x5 VPO C-600914
7x10 AL C-600921
FG C-600922
PL C-600923
VPO C-600924
10x14 AL C-600931
FG C-600932
PL C-600933
VPO C-600934
14x20 AL C-600941
PL C-600943
VPO C-600944

CAUTION PINCH POINTS

3x5 VPO C-961514
7x10 AL C-961521
FG C-961522
PL C-961523
VPO C-961524
10x14 AL C-961531
FG C-961532
PL C-961533
VPO C-961534
14x20 AL C-961541
PL C-961543
VPO C-961544

CAUTION POSSIBLE ASPHYXIATING ATMOSPHERE BEYOND THIS POINT

3x5 VPO C-601014
7x10 AL C-601021
FG C-601022
PL C-601023
VPO C-601024
10x14 AL C-601031
FG C-601032
PL C-601033
VPO C-601034
14x20 AL C-601041
PL C-601043
VPO C-601044

CAUTION POWER DOES NOT SHUT OFF WITH MAIN DISCONNECT USE PANEL MOUNTED MAIN CIRCUIT BREAKER CHECK WITH VOLTMETER BEFORE SERVICING

3x5 VPO C-601114
7x10 AL C-601121
FG C-601122
PL C-601123
VPO C-601124
10x14 AL C-601131
FG C-601132
PL C-601133
VPO C-601134
14x20 AL C-601141
PL C-601143
VPO C-601144

CAUTION PROCESSING AREA NO EATING, DRINKING OR SMOKING PERMITTED BEYOND THIS POINT

3x5 VPO C-601314
7x10 AL C-601321
FG C-601322
PL C-601323
VPO C-601324
10x14 AL C-601331
FG C-601332
PL C-601333
VPO C-601334
14x20 AL C-601341
PL C-601343
VPO C-601344

CAUTION PROPANE EXTREMELY FLAMMABLE CAN CAUSE EYE AND SKIN BURNS AND FROSTBITE KEEP AWAY FROM HEAT, OPEN FLAME OR OTHER SOURCE OF IGNITION. IF CONTACT OCCURS FLUSH WITH Lukewarm Water. USE FACE SHIELD AND GOGGLES WHERE CONTACT IS POSSIBLE

3x5 VPO C-601414
7x10 AL C-601421
FG C-601422
PL C-601423
VPO C-601424
10x14 AL C-601431
FG C-601432
PL C-601433
VPO C-601434
14x20 AL C-601441
PL C-601443
VPO C-601444

CAUTION PROPER EYE WEAR AND FOOT WEAR REQUIRED BEYOND THIS POINT

3x5 VPO C-601514
7x10 AL C-601521
FG C-601522
PL C-601523
VPO C-601524
10x14 AL C-601531
FG C-601532
PL C-601533
VPO C-601534
14x20 AL C-601541
PL C-601543
VPO C-601544

CAUTION PROPERTY PROTECTED BY ELECTRONIC ALARM SYSTEM

3x5 VPO C-601614
7x10 AL C-601621
FG C-601622
PL C-601623
VPO C-601624
10x14 AL C-601631
FG C-601632
PL C-601633
VPO C-601634
14x20 AL C-601641
PL C-601643
VPO C-601644

CAUTION PROTECTIVE CLOTHING MUST BE WORN WHILE WORKING IN THIS AREA

3x5 VPO C-601714
7x10 AL C-601721
FG C-601722
PL C-601723
VPO C-601724
10x14 AL C-601731
FG C-601732
PL C-601733
VPO C-601734
14x20 AL C-601741
PL C-601743
VPO C-601744

CAUTION PROTECTIVE CLOTHING REQUIRED IN THIS AREA

3x5 VPO C-601814
7x10 AL C-601821
FG C-601822
PL C-601823
VPO C-601824
10x14 AL C-601831
FG C-601832
PL C-601833
VPO C-601834
14x20 AL C-601841
PL C-601843
VPO C-601844

CAUTION PROTECTIVE EQUIPMENT REQUIRED

3x5 VPO C-961614
7x10 AL C-961621
FG C-961622
PL C-961623
VPO C-961624
10x14 AL C-961631
FG C-961632
PL C-961633
VPO C-961634
14x20 AL C-961641
PL C-961643
VPO C-961644

CAUTION RADIOACTIVE MATERIALS RADIATION AREA AUTHORIZED PERSONNEL ONLY

3x5 VPO C-660214
7x10 AL C-660221
FG C-660222
PL C-660223
VPO C-660224
10x14 AL C-660231
FG C-660232
PL C-660233
VPO C-660234
14x20 AL C-660241
PL C-660243
VPO C-660244

CAUTION RAIL CAR WHEELS MUST BE CHOCKED

3x5 VPO C-660314
7x10 AL C-660321
FG C-660322
PL C-660323
VPO C-660324
10x14 AL C-660331
FG C-660332
PL C-660333
VPO C-660334
14x20 AL C-660341
PL C-660343
VPO C-660344

CAUTION RESPIRATOR REQUIRED

3x5 VPO C-660414
7x10 AL C-660421
FG C-660422
PL C-660423
VPO C-660424
10x14 AL C-660431
FG C-660432
PL C-660433
VPO C-660434
14x20 AL C-660441
PL C-660443
VPO C-660444

CAUTION RESPIRATORS MUST BE WORN IN THIS AREA

3x5 VPO C-660514
7x10 AL C-660521
FG C-660522
PL C-660523
VPO C-660524
10x14 AL C-660531
FG C-660532
PL C-660533
VPO C-660534
14x20 AL C-660541
PL C-660543
VPO C-660544

CAUTION RESPIRATORS REQUIRED IN THIS AREA

3x5 VPO C-660714
7x10 AL C-660721
FG C-660722
PL C-660723
VPO C-660724
10x14 AL C-660731
FG C-660732
PL C-660733
VPO C-660734
14x20 AL C-660741
PL C-660743
VPO C-660744

CAUTION RESTRICTED ACCESS SUPERVISORS AUTHORIZATION AND PROPER LOCKOUT MANDATORY PRIOR TO CHAMBER (PIT) ENTRY

3x5 VPO C-660814
7x10 AL C-660821
FG C-660822
PL C-660823
VPO C-660824
10x14 AL C-660831
FG C-660832
PL C-660833
VPO C-660834
14x20 AL C-660841
PL C-660843
VPO C-660844

CAUTION RESTRICTED AREA NO EATING, SMOKING OR DRINKING BEYOND THIS POINT

3x5 VPO C-660914
7x10 AL C-660921
FG C-660922
PL C-660923
VPO C-660924
10x14 AL C-660931
FG C-660932
PL C-660933
VPO C-660934
14x20 AL C-660941
PL C-660943
VPO C-660944

CAUTION ROBOT IN OPERATION WHEN LIGHT IS ON

3x5 VPO C-661014
7x10 AL C-661021
FG C-661022
PL C-661023
VPO C-661024
10x14 AL C-661031
FG C-661032
PL C-661033
VPO C-661034
14x20 AL C-661041
PL C-661043
VPO C-661044

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY

THE SIGNS OF A SAFE INDUSTRY

MATERIALS



CAUTION

CAUTION

ROBOT
OPERATING AREA
DO NOT ENTER
AUTHORIZED
PERSONNEL ONLY

3x5 VPO C-661114
7x10 AL C-661121
FG C-661122
PL C-661123
VPO C-661124
10x14 AL C-661131
FG C-661132
PL C-661133
VPO C-661134
14x20 AL C-661141
PL C-661143
VPO C-661144

CAUTION

SAFETY BELT
REQUIRED

3x5 VPO C-710214
7x10 AL C-710221
FG C-710222
PL C-710223
VPO C-710224
10x14 AL C-710231
FG C-710232
PL C-710233
VPO C-710234
14x20 AL C-710241
PL C-710243
VPO C-710244

CAUTION

SAFETY GLASSES
MUST BE WORN
AT ALL TIMES

3x5 VPO C-710314
7x10 AL C-710321
FG C-710322
PL C-710323
VPO C-710324
10x14 AL C-710331
FG C-710332
PL C-710333
VPO C-710334
14x20 AL C-710341
PL C-710343
VPO C-710344

CAUTION

SAFETY GLASSES
MUST BE
WORN WHEN
USING CHEMICALS

3x5 VPO C-710414
7x10 AL C-710421
FG C-710422
PL C-710423
VPO C-710424
10x14 AL C-710431
FG C-710432
PL C-710433
VPO C-710434
14x20 AL C-710441
PL C-710443
VPO C-710444

CAUTION

SAFETY SHOES
REQUIRED
IN THIS AREA

3x5 VPO C-710514
7x10 AL C-710521
FG C-710522
PL C-710523
VPO C-710524
10x14 AL C-710531
FG C-710532
PL C-710533
VPO C-710534
14x20 AL C-710541
PL C-710543
VPO C-710544

CAUTION

SECURE
ALL TANKS
CHAIN CYLINDERS

3x5 VPO C-710614
7x10 AL C-710621
FG C-710622
PL C-710623
VPO C-710624
10x14 AL C-710631
FG C-710632
PL C-710633
VPO C-710634
14x20 AL C-710641
PL C-710643
VPO C-710644

CAUTION

SHUT OFF
MACHINE WHEN
NOT IN USE

3x5 VPO C-710814
7x10 AL C-710821
FG C-710822
PL C-710823
VPO C-710824
10x14 AL C-710831
FG C-710832
PL C-710833
VPO C-710834
14x20 AL C-710841
PL C-710843
VPO C-710844

CAUTION

SILICA DUST HAZARD
AVOID BREATHING DUST WEAR
ASSIGNED PROTECTIVE EQUIPMENT
DO NOT REMAIN IN AREA UNLESS
YOUR WORK REQUIRES IT
BREATHING SILICA DUST MAY
BE HAZARDOUS TO YOUR HEALTH

3x5 VPO C-710914
7x10 AL C-710921
FG C-710922
PL C-710923
VPO C-710924
10x14 AL C-710931
FG C-710932
PL C-710933
VPO C-710934
14x20 AL C-710941
PL C-710943
VPO C-710944

CAUTION

SLIPPERY
FLOOR

3x5 VPO C-711014
7x10 AL C-711021
FG C-711022
PL C-711023
VPO C-711024
10x14 AL C-711031
FG C-711032
PL C-711033
VPO C-711034
14x20 AL C-711041
PL C-711043
VPO C-711044

CAUTION

SLIPPERY
STEPS

3x5 VPO C-711114
7x10 AL C-711121
FG C-711122
PL C-711123
VPO C-711124
10x14 AL C-711131
FG C-711132
PL C-711133
VPO C-711134
14x20 AL C-711141
PL C-711143
VPO C-711144

CAUTION

SLIPPERY
TRIP HAZARD

3x5 VPO C-711214
7x10 AL C-711221
FG C-711222
PL C-711223
VPO C-711224
10x14 AL C-711231
FG C-711232
PL C-711233
VPO C-711234
14x20 AL C-711241
PL C-711243
VPO C-711244

CAUTION

SLIPPERY
WHEN WET

3x5 VPO C-711314
7x10 AL C-711321
FG C-711322
PL C-711323
VPO C-711324
10x14 AL C-711331
FG C-711332
PL C-711333
VPO C-711334
14x20 AL C-711341
PL C-711343
VPO C-711344

CAUTION

SLOW

3x5 VPO C-711514
7x10 AL C-711521
FG C-711522
PL C-711523
VPO C-711524
10x14 AL C-711531
FG C-711532
PL C-711533
VPO C-711534
14x20 AL C-711541
PL C-711543
VPO C-711544

CAUTION

SOUND LEVELS MAY BE
IN EXCESS OF 85dba
HEARING PROTECTION
IS RECOMMENDED

3x5 VPO C-711614
7x10 AL C-711621
FG C-711622
PL C-711623
VPO C-711624
10x14 AL C-711631
FG C-711632
PL C-711633
VPO C-711634
14x20 AL C-711641
PL C-711643
VPO C-711644

CAUTION

SPEED
BUMP

3x5 VPO C-711714
7x10 AL C-711721
FG C-711722
PL C-711723
VPO C-711724
10x14 AL C-711731
FG C-711732
PL C-711733
VPO C-711734
14x20 AL C-711741
PL C-711743
VPO C-711744

CAUTION

SPEED BUMP
5 MILES
PER HOUR

3x5 VPO C-711814
7x10 AL C-711821
FG C-711822
PL C-711823
VPO C-711824
10x14 AL C-711831
FG C-711832
PL C-711833
VPO C-711834
14x20 AL C-711841
PL C-711843
VPO C-711844

CAUTION

STAND CLEAR
OF DOOR

3x5 VPO C-712114
7x10 AL C-712121
FG C-712122
PL C-712123
VPO C-712124
10x14 AL C-712131
FG C-712132
PL C-712133
VPO C-712134
14x20 AL C-712141
PL C-712143
VPO C-712144

CAUTION

STATIC
CONTROL
AREA

3x5 VPO C-712214
7x10 AL C-712221
FG C-712222
PL C-712223
VPO C-712224
10x14 AL C-712231
FG C-712232
PL C-712233
VPO C-712234
14x20 AL C-712241
PL C-712243
VPO C-712244

CAUTION

STAY CLEAR
MOVING
EQUIPMENT

3x5 VPO C-712414
7x10 AL C-712421
FG C-712422
PL C-712423
VPO C-712424
10x14 AL C-712431
FG C-712432
PL C-712433
VPO C-712434
14x20 AL C-712441
PL C-712443
VPO C-712444

CAUTION

STAY CLEAR
WHEN LIFT
IS OPERATING

3x5 VPO C-712514
7x10 AL C-712521
FG C-712522
PL C-712523
VPO C-712524
10x14 AL C-712531
FG C-712532
PL C-712533
VPO C-712534
14x20 AL C-712541
PL C-712543
VPO C-712544

CAUTION

STEP
DOWN

3x5 VPO C-712714
7x10 AL C-712721
FG C-712722
PL C-712723
VPO C-712724
10x14 AL C-712731
FG C-712732
PL C-712733
VPO C-712734
14x20 AL C-712741
PL C-712743
VPO C-712744

CAUTION

STOP MACHINE
BEFORE MAKING
ADJUSTMENT

3x5 VPO C-712914
7x10 AL C-712921
FG C-712922
PL C-712923
VPO C-712924
10x14 AL C-712931
FG C-712932
PL C-712933
VPO C-712934
14x20 AL C-712941
PL C-712943
VPO C-712944

CAUTION

STEP UP

3x5 VPO C-712314
7x10 AL C-712321
FG C-712322
PL C-712323
VPO C-712324
10x14 AL C-712331
FG C-712332
PL C-712333
VPO C-712334
14x20 AL C-712341
PL C-712343
VPO C-712344

CAUTION

THIS AREA PROTECTED BY
CO2 FIRE EXTINGUISHER SYSTEM
LEAVE IMMEDIATELY UPON WARNING
OF DISCHARGE. DO NOT RE-ENTER
UNTIL FRESH AIR IS RESTORED

3x5 VPO C-810214
7x10 AL C-810221
FG C-810222
PL C-810223
VPO C-810224
10x14 AL C-810231
FG C-810232
PL C-810233
VPO C-810234
14x20 AL C-810241
PL C-810243
VPO C-810244

CAUTION

THIS BUILDING
CONTAINS
PCB STORAGE

3x5 VPO C-810314
7x10 AL C-810321
FG C-810322
PL C-810323
VPO C-810324
10x14 AL C-810331
FG C-810332
PL C-810333
VPO C-810334
14x20 AL C-810341
PL C-810343
VPO C-810344

CAUTION

THIS DOOR
FOR EMERGENCY
USE ONLY

3x5 VPO C-810514
7x10 AL C-810521
FG C-810522
PL C-810523
VPO C-810524
10x14 AL C-810531
FG C-810532
PL C-810533
VPO C-810534
14x20 AL C-810541
PL C-810543
VPO C-810544

CAUTION

THIS DOOR
MUST BE
KEPT CLOSED

3x5 VPO C-810614
7x10 AL C-810621
FG C-810622
PL C-810623
VPO C-810624
10x14 AL C-810631
FG C-810632
PL C-810633
VPO C-810634
14x20 AL C-810641
PL C-810643
VPO C-810644

CAUTION

THIS EQUIPMENT
IS SUPPLIED BY
MORE THAN ONE
POWER SOURCE

3x5 VPO C-810814
7x10 AL C-810821
FG C-810822
PL C-810823
VPO C-810824
10x14 AL C-810831
FG C-810832
PL C-810833
VPO C-810834
14x20 AL C-810841
PL C-810843
VPO C-810844

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY

• If You Don't See It, We Can Make It!

• Custom Jobs Our Specialty...Please Call For A Quote!

CAUTION



THE SIGNS OF A SAFE INDUSTRY

MATERIALS



CAUTION

THIS MATERIAL
CONTAINS
FORMALDEHYDE
A CANCER
SUSPECT AGENT

3x5 VPO C-811214
7x10 AL C-811221
FG C-811222
PL C-811223
VPO C-811224
10x14 AL C-811231
FG C-811232
PL C-811233
VPO C-811234
14x20 AL C-811241
PL C-811243
VPO C-811244

CAUTION

THIS PANEL
POWERED BY MORE
THAN ONE POWER
SOURCE

3x5 VPO C-811314
7x10 AL C-811321
FG C-811322
PL C-811323
VPO C-811324
10x14 AL C-811331
FG C-811332
PL C-811333
VPO C-811334
14x20 AL C-811341
PL C-811343
VPO C-811344

CAUTION

THIS ROOM IS PROTECTED
BY CO2 FIRE EXTINGUISHER
SYSTEM. LEAVE IMMEDIATELY
UPON SYSTEM DISCHARGE.
DO NOT RE-ENTER UNTIL
FRESH AIR IS RESTORED.

3x5 VPO C-811414
7x10 AL C-811421
FG C-811422
PL C-811423
VPO C-811424
10x14 AL C-811431
FG C-811432
PL C-811433
VPO C-811434
14x20 AL C-811441
PL C-811443
VPO C-811444

CAUTION

THIS ROOM IS PROTECTED
BY HALON FIRE EXTINGUISHER
SYSTEM. LEAVE IMMEDIATELY
UPON SYSTEM DISCHARGE.
DO NOT RE-ENTER UNTIL
FRESH AIR IS RESTORED.

3x5 VPO C-811514
7x10 AL C-811521
FG C-811522
PL C-811523
VPO C-811524
10x14 AL C-811531
FG C-811532
PL C-811533
VPO C-811534
14x20 AL C-811541
PL C-811543
VPO C-811544

CAUTION

THIS SPACE MUST
BE KEPT CLEAR
AT ALL TIMES

3x5 VPO C-811614
7x10 AL C-811621
FG C-811622
PL C-811623
VPO C-811624
10x14 AL C-811631
FG C-811632
PL C-811633
VPO C-811634
14x20 AL C-811641
PL C-811643
VPO C-811644

CAUTION

THIS UNIT
MAY START
AUTOMATICALLY
AT ANY TIME

3x5 VPO C-811714
7x10 AL C-811721
FG C-811722
PL C-811723
VPO C-811724
10x14 AL C-811731
FG C-811732
PL C-811733
VPO C-811734
14x20 AL C-811741
PL C-811743
VPO C-811744

CAUTION

THIS UNIT
STARTS
WITHOUT
WARNING

3x5 VPO C-811814
7x10 AL C-811821
FG C-811822
PL C-811823
VPO C-811824
10x14 AL C-811831
FG C-811832
PL C-811833
VPO C-811834
14x20 AL C-811841
PL C-811843
VPO C-811844

CAUTION

THIS VEHICLE
MAKES
FREQUENT
STOPS

3x5 VPO C-811914
7x10 AL C-811921
FG C-811922
PL C-811923
VPO C-811924
10x14 AL C-811931
FG C-811932
PL C-811933
VPO C-811934
14x20 AL C-811941
PL C-811943
VPO C-811944

CAUTION

THIS VEHICLE
MAKES WIDE
RIGHT TURNS

3x5 VPO C-812014
7x10 AL C-812021
FG C-812022
PL C-812023
VPO C-812024
10x14 AL C-812031
FG C-812032
PL C-812033
VPO C-812034
14x20 AL C-812041
PL C-812043
VPO C-812044

CAUTION

THIS WATER IS UNSAFE
DO NOT USE
FOR DRINKING,
WASHING OR COOKING

3x5 VPO C-812114
7x10 AL C-812121
FG C-812122
PL C-812123
VPO C-812124
10x14 AL C-812131
FG C-812132
PL C-812133
VPO C-812134
14x20 AL C-812141
PL C-812143
VPO C-812144

CAUTION

TOXIC
VAPORS

3x5 VPO C-812414
7x10 AL C-812421
FG C-812422
PL C-812423
VPO C-812424
10x14 AL C-812431
FG C-812432
PL C-812433
VPO C-812434
14x20 AL C-812441
PL C-812443
VPO C-812444

CAUTION

TOXIC/HAZARDOUS CHEMICALS
ARE USED IN THIS WORKPLACE
SAFETY DATA SHEETS ARE
AVAILABLE IN THE
SUPERVISORS OFFICE

3x5 VPO C-812514
7x10 AL C-812521
FG C-812522
PL C-812523
VPO C-812524
10x14 AL C-812531
FG C-812532
PL C-812533
VPO C-812534
14x20 AL C-812541
PL C-812543
VPO C-812544

CAUTION

TREATED WATER SYSTEM
DO NOT DUMP WASTE
INTO THIS DRAIN

3x5 VPO C-812614
7x10 AL C-812621
FG C-812622
PL C-812623
VPO C-812624
10x14 AL C-812631
FG C-812632
PL C-812633
VPO C-812634
14x20 AL C-812641
PL C-812643
VPO C-812644

CAUTION

TRIP
HAZARD AREA

3x5 VPO C-812714
7x10 AL C-812721
FG C-812722
PL C-812723
VPO C-812724
10x14 AL C-812731
FG C-812732
PL C-812733
VPO C-812734
14x20 AL C-812741
PL C-812743
VPO C-812744

CAUTION

TRIPPING
HAZARD

3x5 VPO C-812814
7x10 AL C-812821
FG C-812822
PL C-812823
VPO C-812824
10x14 AL C-812831
FG C-812832
PL C-812833
VPO C-812834
14x20 AL C-812841
PL C-812843
VPO C-812844

CAUTION

TRUCK WHEELS
MUST BE
CHOCKED

3x5 VPO C-813014
7x10 AL C-813021
FG C-813022
PL C-813023
VPO C-813024
10x14 AL C-813031
FG C-813032
PL C-813033
VPO C-813034
14x20 AL C-813041
PL C-813043
VPO C-813044

CAUTION

TURN EQUIPMENT
POWER OFF
WHEN NOT IN USE

3x5 VPO C-813114
7x10 AL C-813121
FG C-813122
PL C-813123
VPO C-813124
10x14 AL C-813131
FG C-813132
PL C-813133
VPO C-813134
14x20 AL C-813141
PL C-813143
VPO C-813144

CAUTION

TURN OFF 2-WAY
RADIO BEFORE
ENTERING ROOM

3x5 VPO C-813214
7x10 AL C-813221
FG C-813222
PL C-813223
VPO C-813224
10x14 AL C-813231
FG C-813232
PL C-813233
VPO C-813234
14x20 AL C-813241
PL C-813243
VPO C-813244

CAUTION

ULTRAVIOLET LIGHT
DO NOT LOOK
AT LIGHT

3x5 VPO C-860114
7x10 AL C-860121
FG C-860122
PL C-860123
VPO C-860124
10x14 AL C-860131
FG C-860132
PL C-860133
VPO C-860134
14x20 AL C-860141
PL C-860143
VPO C-860144

CAUTION

ULTRAVIOLET LIGHT
USE
EYE PROTECTION

3x5 VPO C-860214
7x10 AL C-860221
FG C-860222
PL C-860223
VPO C-860224
10x14 AL C-860231
FG C-860232
PL C-860233
VPO C-860234
14x20 AL C-860241
PL C-860243
VPO C-860244

CAUTION

UNDERGROUND
PIPELINE
DO NOT EXCAVATE

3x5 VPO C-860414
7x10 AL C-860421
FG C-860422
PL C-860423
VPO C-860424
10x14 AL C-860431
FG C-860432
PL C-860433
VPO C-860434
14x20 AL C-860441
PL C-860443
VPO C-860444

CAUTION

UNLAWFUL
TO DISPENSE FUEL
INTO PLASTIC OR
GLASS CONTAINERS

3x5 VPO C-860514
7x10 AL C-860521
FG C-860522
PL C-860523
VPO C-860524
10x14 AL C-860531
FG C-860532
PL C-860533
VPO C-860534
14x20 AL C-860541
PL C-860543
VPO C-860544

CAUTION

UNLAWFUL TO OPERATE
THIS EQUIPMENT
WITHIN 10 FEET OF
HIGH VOLTAGE LINES

3x5 VPO C-860614
7x10 AL C-860621
FG C-860622
PL C-860623
VPO C-860624
10x14 AL C-860631
FG C-860632
PL C-860633
VPO C-860634
14x20 AL C-860641
PL C-860643
VPO C-860644

CAUTION

UNSUPPORTED
ROOF AREA
KEEP OUT

3x5 VPO C-860714
7x10 AL C-860721
FG C-860722
PL C-860723
VPO C-860724
10x14 AL C-860731
FG C-860732
PL C-860733
VPO C-860734
14x20 AL C-860741
PL C-860743
VPO C-860744

CAUTION

USE
HANDRAIL

3x5 VPO C-860814
7x10 AL C-860821
FG C-860822
PL C-860823
VPO C-860824
10x14 AL C-860831
FG C-860832
PL C-860833
VPO C-860834
14x20 AL C-860841
PL C-860843
VPO C-860844

CAUTION

USE STATIC
GROUNDING
DEVICES

3x5 VPO C-861014
7x10 AL C-861021
FG C-861022
PL C-861023
VPO C-861024
10x14 AL C-861031
FG C-861032
PL C-861033
VPO C-861034
14x20 AL C-861041
PL C-861043
VPO C-861044

CAUTION

WATCH
FOR
LIFT TRUCKS

3x5 VPO C-920114
7x10 AL C-920121
FG C-920122
PL C-920123
VPO C-920124
10x14 AL C-920131
FG C-920132
PL C-920133
VPO C-920134
14x20 AL C-920141
PL C-920143
VPO C-920144

CAUTION

WATCH
FOR
VEHICLES

3x5 VPO C-920314
7x10 AL C-920321
FG C-920322
PL C-920323
VPO C-920324
10x14 AL C-920331
FG C-920332
PL C-920333
VPO C-920334
14x20 AL C-920341
PL C-920343
VPO C-920344

1.800.527.8775

www.kcsupply.com

1.800.KC.SUPPLY



CAUTION

CAUTION WATCH YOUR STEP	CAUTION WET FLOORS	CAUTION WEAR EAR PROTECTION	CAUTION WEAR EYE PROTECTION WHEN OPERATING THIS MACHINE	CAUTION WEAR EYE PROTECTION WHILE OPERATING	CAUTION WEAR FACE SHIELD OR GOGGLES WHILE OPERATING THIS MACHINE	CAUTION WEAR GOGGLES OR SAFETY GLASSES WITH FACE SHIELD WHEN USING GRINDER
3x5 VPO C-920614 7x10 AL C-920621 FG C-920622 PL C-920623 VPO C-920624 10x14 AL C-920631 FG C-920632 PL C-920633 VPO C-920634 14x20 AL C-920641 PL C-920643 VPO C-920644	3x5 VPO C-922414 7x10 AL C-922421 FG C-922422 PL C-922423 VPO C-922424 10x14 AL C-922431 FG C-922432 PL C-922433 VPO C-922434 14x20 AL C-922441 PL C-922443 VPO C-922444	3x5 VPO C-920814 7x10 AL C-920821 FG C-920822 PL C-920823 VPO C-920824 10x14 AL C-920831 FG C-920832 PL C-920833 VPO C-920834 14x20 AL C-920841 PL C-920843 VPO C-920844	3x5 VPO C-921114 7x10 AL C-921121 FG C-921122 PL C-921123 VPO C-921124 10x14 AL C-921131 FG C-921132 PL C-921133 VPO C-921134 14x20 AL C-921141 PL C-921143 VPO C-921144	3x5 VPO C-921214 7x10 AL C-921221 FG C-921222 PL C-921223 VPO C-921224 10x14 AL C-921231 FG C-921232 PL C-921233 VPO C-921234 14x20 AL C-921241 PL C-921243 VPO C-921244	3x5 VPO C-921414 7x10 AL C-921421 FG C-921422 PL C-921423 VPO C-921424 10x14 AL C-921431 FG C-921432 PL C-921433 VPO C-921434 14x20 AL C-921441 PL C-921443 VPO C-921444	3x5 VPO C-921514 7x10 AL C-921521 FG C-921522 PL C-921523 VPO C-921524 10x14 AL C-921531 FG C-921532 PL C-921533 VPO C-921534 14x20 AL C-921541 PL C-921543 VPO C-921544

CAUTION WEAR GOGGLES WHEN USING THIS MACHINE	CAUTION WEAR SAFETY SHOES IN THIS AREA	CAUTION WEAR YOUR RESPIRATOR	CAUTION WELDING AREA	CAUTION WHEN ALARM SOUNDS VACATE ROOM CO2 BEING DISCHARGED	CAUTION WHEN ALARM SOUNDS VACATE ROOM HALON 1301 BEING DISCHARGED	CAUTION YOU ARE POSITIVELY FORBIDDEN TO WORK WITH ACID WITHOUT GOGGLES
3x5 VPO C-921614 7x10 AL C-921621 FG C-921622 PL C-921623 VPO C-921624 10x14 AL C-921631 FG C-921632 PL C-921633 VPO C-921634 14x20 AL C-921641 PL C-921643 VPO C-921644	3x5 VPO C-921914 7x10 AL C-921921 FG C-921922 PL C-921923 VPO C-921924 10x14 AL C-921931 FG C-921932 PL C-921933 VPO C-921934 14x20 AL C-921941 PL C-921943 VPO C-921944	3x5 VPO C-922014 7x10 AL C-922021 FG C-922022 PL C-922023 VPO C-922024 10x14 AL C-922031 FG C-922032 PL C-922033 VPO C-922034 14x20 AL C-922041 PL C-922043 VPO C-922044	3x5 VPO C-922214 7x10 AL C-922221 FG C-922222 PL C-922223 VPO C-922224 10x14 AL C-922231 FG C-922232 PL C-922233 VPO C-922234 14x20 AL C-922241 PL C-922243 VPO C-922244	3x5 VPO C-922614 7x10 AL C-922621 FG C-922622 PL C-922623 VPO C-922624 10x14 AL C-922631 FG C-922632 PL C-922633 VPO C-922634 14x20 AL C-922641 PL C-922643 VPO C-922644	3x5 VPO C-922714 7x10 AL C-922721 FG C-922722 PL C-922723 VPO C-922724 10x14 AL C-922731 FG C-922732 PL C-922733 VPO C-922734 14x20 AL C-922741 PL C-922743 VPO C-922744	3x5 VPO C-980114 7x10 AL C-980121 FG C-980122 PL C-980123 VPO C-980124 10x14 AL C-980131 FG C-980132 PL C-980133 VPO C-980134 14x20 AL C-980141 PL C-980143 VPO C-980144

CAUTION PICTORALS

CAUTION CORROSIVE MATERIALS AND LIQUIDS USE HAND PROTECTION 	CAUTION DESCEND THIS LADDER FACING STEPS 	CAUTION DO NOT ENTER WHILE MACHINERY IN MOTION 	CAUTION DO NOT OPERATE THIS MACHINE WITHOUT EYE PROTECTION 	CAUTION EAR PROTECTION AREA 	CAUTION EAR PROTECTION REQUIRED IN THIS AREA 	CAUTION EAR PROTECTION REQUIRED NOISE LEVEL IS ABOVE 85dbA
5x12 AL CP-083871 PL CP-083873 VPO CP-083874 7x17 AL CP-083881 PL CP-083883 VPO CP-083884	5x12 AL CP-110271 PL CP-110273 VPO CP-110274 7x17 AL CP-110281 PL CP-110283 VPO CP-110284	5x12 AL CP-111471 PL CP-111473 VPO CP-111474 7x17 AL CP-111481 PL CP-111483 VPO CP-111484	5x12 AL CP-112571 PL CP-112573 VPO CP-112574 7x17 AL CP-112581 PL CP-112583 VPO CP-112584	5x12 AL CP-160371 PL CP-160373 VPO CP-160374 7x17 AL CP-160381 PL CP-160383 VPO CP-160384	5x12 AL CP-160871 PL CP-160873 VPO CP-160874 7x17 AL CP-160881 PL CP-160883 VPO CP-160884	5x12 AL CP-161071 PL CP-161073 VPO CP-161074 7x17 AL CP-161081 PL CP-161083 VPO CP-161084
CAUTION EYE PROTECTION AREA 	CAUTION EYE PROTECTION REQUIRED IN THIS AREA 	CAUTION FACE MASK MUST BE WORN IN SPRAY BOOTH 	CAUTION FOOT PROTECTION REQUIRED IN THIS AREA 	CAUTION HARD HAT AREA 	CAUTION HARD HATS REQUIRED IN THIS AREA 	CAUTION RESPIRATORS MUST BE WORN IN THIS AREA
5x12 AL CP-162371 PL CP-162373 VPO CP-162374 7x17 AL CP-162381 PL CP-162383 VPO CP-162384	5x12 AL CP-163071 PL CP-163073 VPO CP-163074 7x17 AL CP-163081 PL CP-163083 VPO CP-163084	5x12 AL CP-260271 PL CP-260273 VPO CP-260274 7x17 AL CP-260281 PL CP-260283 VPO CP-260284	5x12 AL CP-261471 PL CP-261473 VPO CP-261474 7x17 AL CP-261481 PL CP-261483 VPO CP-261484	5x12 AL CP-370471 PL CP-370473 VPO CP-370474 7x17 AL CP-370481 PL CP-370483 VPO CP-370484	5x12 AL CP-370971 PL CP-370973 VPO CP-370974 7x17 AL CP-370981 PL CP-370983 VPO CP-370984	5x12 AL CP-660671 PL CP-660673 VPO CP-660674 7x17 AL CP-660681 PL CP-660683 VPO CP-660684
CAUTION SLIPPERY WHEN WET 	CAUTION WATCH OUT FOR FORK TRUCKS 	CAUTION WATCH YOUR STEP 	CAUTION WEAR EAR PROTECTION 	CAUTION WEAR GOGGLES WHEN USING THIS MACHINE 	CAUTION WEAR YOUR RESPIRATOR 	CAUTION WATCH FOR WORK VEHICLES
5x12 AL CP-711471 PL CP-711473 VPO CP-711474 7x17 AL CP-711481 PL CP-711483 VPO CP-711484	5x12 AL CP-966371 PL CP-966373 VPO CP-966374 7x17 AL CP-966381 PL CP-966383 VPO CP-966384	5x12 AL CP-966771 PL CP-966773 VPO CP-966774 7x17 AL CP-966781 PL CP-966783 VPO CP-966784	5x12 AL CP-920971 PL CP-920973 VPO CP-920974 7x17 AL CP-920981 PL CP-920983 VPO CP-920984	5x12 AL CP-921771 PL CP-921773 VPO CP-921774 7x17 AL CP-921781 PL CP-921783 VPO CP-921784	5x12 AL CP-922171 PL CP-922173 VPO CP-922174 7x17 AL CP-922181 PL CP-922183 VPO CP-922184	5x12 AL CP-966271 PL CP-966273 VPO CP-966274 7x17 AL CP-966281 PL CP-966283 VPO CP-966284

- If You Don't See It, We Can Make It!
- Custom Jobs Our Specialty...Please Call For A Quote!